

DEBRIS FIELD-N8178Y

2020-12-06




↑
South

79 YDS (FIRE IMPACT TO LAST PART)





NORTH



EXTENDING 10 YARDS SOUTH OF DIRECTION OF TRAVEL, THERE WAS A SURFACE FIRE.
WINGS AND FUSELAGE WERE NOT BURNED BY FIRE, MINIMAL BURN SCARS ON ENGINE.

089 DIRECTION OF TRAVEL FOR APPROXIMATELY 79 YARDS