

Select Flight 12/14/20: KMYF-KLXV ▾

Go

Event Log

Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:12:46	1	NO_EVENT	1	L-ACS	0	0	0
2020-12-14 00:12:46	177	EPDS_SYS_BATT_DISCHARGING	1	L-ACS	0	0	0
2020-12-14 00:12:46	178	EPDS_START_BATT_DISCHARGING	1	L-ACS	0	0	0
2020-12-14 00:12:46	540	FUEL_AUTO_LAT_CG_TRANSFER_DISABLE	1	L-ACS	0	0	0
2020-12-14 00:12:46	564	FUEL_GAUGING_FAIL_LEFT	1	L-ACS	0	0	0
2020-12-14 00:12:46	565	FUEL_GAUGING_FAIL_RIGHT	1	L-ACS	0	0	0
2020-12-14 00:12:46	700	L_WINDSHIELD_HEAT_OFF	1	L-ACS	0	0	0
2020-12-14 00:12:46	701	R_WINDSHIELD_HEAT_OFF	1	L-ACS	0	0	0
2020-12-14 00:12:46	730	MASTER_CAUTION_DISABLE	1	L-ACS	0	0	0
2020-12-14 00:12:46	965	ACS_AI_BIT_CONDO_OG1_WRAP_FAIL	1	L-ACS	0	0	0
2020-12-14 00:12:46	978	ACS_AI_BIT_CONVO_3_WRAP_FAIL	1	L-ACS	0	0	0
2020-12-14 00:12:46	1071	ACS_DO_ON_GROUND_2_FAIL	1	L-ACS	0	0	0
2020-12-14 00:12:46	1075	ACS_DO_IN_AIR_FAIL	1	L-ACS	0	0	0
2020-12-14 00:12:46	1076	ACS_DO_L_ENGINE_STOP_FAIL	1	L-ACS	0	0	0
2020-12-14 00:12:46	1079	ACS_DO_R_GCU_RESET_FAIL	1	L-ACS	0	0	0
2020-12-14 00:12:46	1103	EPDS_ECB_1_09_LOCKED	1	L-ACS	0	0	0
2020-12-14 00:12:46	8321	EPDS_ECB_1_12_LOCKED	1	L-ACS	0	0	0
2020-12-14 00:12:46	1127	EPDS_ECB_2_09_LOCKED	1	L-ACS	0	0	0
2020-12-14 00:12:46	1164	EPDS_ECB_4_08_LOCKED	1	L-ACS	0	0	0
2020-12-14 00:12:46	8279	EPDS_ECB_4_10_LOCKED	1	L-ACS	0	0	0
2020-12-14 00:12:46	1169	EPDS_ECB_4_13_LOCKED	1	L-ACS	0	0	0
2020-12-14 00:12:46	1170	EPDS_ECB_4_14_LOCKED	1	L-ACS	0	0	0
2020-12-14 00:12:46	1188	EPDS_ECB_4_32_LOCKED	1	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:12:46	1199	EPDS_ECB_5_06_LOCKED	1	L-ACS	0	0	0
2020-12-14 00:12:46	1201	EPDS_ECB_5_08_LOCKED	1	L-ACS	0	0	0
2020-12-14 00:12:46	1203	EPDS_ECB_5_10_LOCKED	1	L-ACS	0	0	0
2020-12-14 00:12:46	1204	EPDS_ECB_5_11_LOCKED	1	L-ACS	0	0	0
2020-12-14 00:12:46	1207	EPDS_ECB_5_14_LOCKED	1	L-ACS	0	0	0
2020-12-14 00:12:46	8291	EPDS_ECB_5_23_LOCKED	1	L-ACS	0	0	0
2020-12-14 00:12:46	1379	ONSIDE_STALL_SYSTEM_FAILURE	1	L-ACS	0	0	0
2020-12-14 00:12:46	1380	OFFSIDE_STALL_SYSTEM_FAILURE	1	L-ACS	0	0	0
2020-12-14 00:12:46	1466	PITCH_POST_BIT_IN_PROGRESS	1	L-ACS	0	0	0
2020-12-14 00:12:46	1467	PITCH_POST_BIT_FAILURE	1	L-ACS	0	0	0
2020-12-14 00:12:46	1468	PITCH_PERIODIC_BIT_IN_PROGRESS	1	L-ACS	0	0	0
2020-12-14 00:12:46	8166	PITCH_PERIODIC_BIT_FAILURE	1	L-ACS	0	0	0
2020-12-14 00:12:46	8167	PITCH_MAINT_BIT_IN_PROGRESS	1	L-ACS	0	0	0
2020-12-14 00:12:46	1471	PITCH_MAINT_BIT_IN_FAILURE	1	L-ACS	0	0	0
2020-12-14 00:12:46	1475	STICK_PUSHER_FAIL	1	L-ACS	0	0	0
2020-12-14 00:12:46	1480	PITCH_AP_EXCEEDANCE_FAIL	1	L-ACS	0	0	0
2020-12-14 00:12:46	1482	PITCH_AP_DISCONNECT	1	L-ACS	0	0	0
2020-12-14 00:12:46	8168	YAW_POST_BIT_IN_PROGRESS	1	L-ACS	0	0	0
2020-12-14 00:12:46	1520	YAW_PERIODIC_BIT_IN_PROGRESS	1	L-ACS	0	0	0
2020-12-14 00:12:46	1522	YAW_MAINT_BIT_IN_PROGRESS	1	L-ACS	0	0	0
2020-12-14 00:12:46	1532	YAW_AP_EXCEEDANCE_FAIL	1	L-ACS	0	0	0
2020-12-14 00:12:46	1534	YAW_YD_DISCONNECT	1	L-ACS	0	0	0
2020-12-14 00:12:46	8242	YAW_YAWRATE_INVALID	1	L-ACS	0	0	0
2020-12-14 00:12:46	1551	YAW_YAWRATE_MISSING	1	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:12:46	1554	YAW_ROLLRATE_INVALID	1	L-ACS	0	0	0
2020-12-14 00:12:46	1555	YAW_ROLLRATE_MISSING	1	L-ACS	0	0	0
2020-12-14 00:12:46	1558	YAW_PITCHRATE_INVALID	1	L-ACS	0	0	0
2020-12-14 00:12:46	1559	YAW_PITCHRATE_MISSING	1	L-ACS	0	0	0
2020-12-14 00:12:46	1562	YAW_ISS_RATE_ERROR	1	L-ACS	0	0	0
2020-12-14 00:12:46	1569	ROLL_PREFLIGHT_BIT_FAILURE	1	L-ACS	0	0	0
2020-12-14 00:12:46	1570	ROLL_POST_BIT_IN_PROGRESS	1	L-ACS	0	0	0
2020-12-14 00:12:46	1571	ROLL_POST_BIT_FAILURE	1	L-ACS	0	0	0
2020-12-14 00:12:46	1572	ROLL_PERIODIC_BIT_IN_PROGRESS	1	L-ACS	0	0	0
2020-12-14 00:12:46	1573	ROLL_PERIODIC_BIT_FAILURE	1	L-ACS	0	0	0
2020-12-14 00:12:46	1574	ROLL_MAINT_BIT_IN_PROGRESS	1	L-ACS	0	0	0
2020-12-14 00:12:46	1575	ROLL_MAINT_BIT_IN_FAILURE	1	L-ACS	0	0	0
2020-12-14 00:12:46	1584	ROLL_AP_EXCEEDANCE_FAIL	1	L-ACS	0	0	0
2020-12-14 00:12:46	1586	ROLL_AP_DISCONNECT	1	L-ACS	0	0	0
2020-12-14 00:12:46	1743	L_AHRS_BUS_DATA_FAIL	1	L-ACS	0	0	0
2020-12-14 00:12:46	1744	R_AHRS_BUS_DATA_FAIL	1	L-ACS	0	0	0
2020-12-14 00:12:46	1874	PITCH_NORMACCELERATION_INVALID	1	L-ACS	0	0	0
2020-12-14 00:12:46	1875	PITCH_NORMACCELERATION_MISSING	1	L-ACS	0	0	0
2020-12-14 00:12:46	1876	PITCH_NORMACCELERATION_ENV	1	L-ACS	0	0	0
2020-12-14 00:12:46	1878	PITCH_LONGACCELERATION_INVALID	1	L-ACS	0	0	0
2020-12-14 00:12:46	1879	PITCH_LONGACCELERATION_MISSING	1	L-ACS	0	0	0
2020-12-14 00:12:46	1882	PITCH_LATACCELERATION_INVALID	1	L-ACS	0	0	0
2020-12-14 00:12:46	1883	PITCH_LATACCELERATION_MISSING	1	L-ACS	0	0	0
2020-12-14 00:12:46	1886	PITCH_ISS_ACCEL_ERROR	1	L-ACS	0	0	0
	1913	ROLL_MAGNETICHEADING_INVALID	1	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:12:46							
2020-12-14 00:12:46	1914	ROLL_MAGNETICHEADING_MISSING	1	L-ACS	0	0	0
2020-12-14 00:12:46	1917	ROLL_ROLLANGLE_INVALID	1	L-ACS	0	0	0
2020-12-14 00:12:46	1918	ROLL_ROLLANGLE_MISSING	1	L-ACS	0	0	0
2020-12-14 00:12:46	1921	ROLL_PITCHANGLE_INVALID	1	L-ACS	0	0	0
2020-12-14 00:12:46	1922	ROLL_PITCHANGLE_MISSING	1	L-ACS	0	0	0
2020-12-14 00:12:46	1925	ROLL_ISS_ANGLE_ERROR	1	L-ACS	0	0	0
2020-12-14 00:12:46	1935	ROLL_RADARALTITUDE_MISSING	1	L-ACS	0	0	0
2020-12-14 00:12:46	1938	ROLL_CMD_ANG_NAV_ERROR	1	L-ACS	0	0	0
2020-12-14 00:12:46	1946	ROLL_VELOCITY_NS_MISSING	1	L-ACS	0	0	0
2020-12-14 00:12:46	1949	ROLL_VELOCITY_EW_MISSING	1	L-ACS	0	0	0
2020-12-14 00:12:46	1951	ROLL_VELOCITY_NS_EW_ERROR	1	L-ACS	0	0	0
2020-12-14 00:12:46	1969	* L_PFD_L_AHRS_FAIL	1	L-ACS	0	0	0
2020-12-14 00:12:46	1972	* L_PFD_R_AHRS_FAIL	1	L-ACS	0	0	0
2020-12-14 00:12:46	1984	* L_PFD_ACTIVE TRANSPONDER_ALT_MODE	1	L-ACS	0	0	0
2020-12-14 00:12:46	1997	L_PFD_TAWS_FAIL	1	L-ACS	0	0	0
2020-12-14 00:12:46	2010	L_PFD_R_TRANSPONDER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:12:46	2034	R_PFD_L_AHRS_FAIL	1	L-ACS	0	0	0
2020-12-14 00:12:46	2037	R_PFD_R_AHRS_FAIL	1	L-ACS	0	0	0
2020-12-14 00:12:46	2049	R_PFD_ACTIVE TRANSPONDER_ALT_MODE	1	L-ACS	0	0	0
2020-12-14 00:12:46	2062	R_PFD_TAWS_FAIL	1	L-ACS	0	0	0
2020-12-14 00:12:46	2075	R_PFD_R_TRANSPONDER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:12:46	2203	L_AHRS_INIT_IN_PROGRESS	1	L-ACS	0	0	0
2020-12-14 00:12:46	2246	R_AHRS_INIT_IN_PROGRESS	1	L-ACS	0	0	0
	8169	Ecb:Left AOA Processor	1	ECBU	0	0	5

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:12:46							
2020-12-14 00:12:46	8169	Ecb:Left AOA Processor	1	ECBU	0	0	6
2020-12-14 00:12:46	8170	Ecb:TCAS II :SKYWATCH	1	ECBU	0	0	5
2020-12-14 00:12:46	8170	Ecb:TCAS II :SKYWATCH	1	ECBU	0	0	6
2020-12-14 00:12:46	8171	Ecb:L CSP	1	ECBU	0	0	5
2020-12-14 00:12:46	8171	Ecb:L CSP	1	ECBU	0	0	6
2020-12-14 00:12:46	8172	Ecb:Auto O2	1	ECBU	0	0	5
2020-12-14 00:12:46	8172	Ecb:Auto O2	1	ECBU	0	0	6
2020-12-14 00:12:46	8173	Ecb:L AHRS - 1	1	ECBU	0	0	5
2020-12-14 00:12:46	8173	Ecb:L AHRS - 1	1	ECBU	0	0	6
2020-12-14 00:12:46	8174	Ecb:L ADC - 1	1	ECBU	0	0	5
2020-12-14 00:12:46	8174	Ecb:L ADC - 1	1	ECBU	0	0	6
2020-12-14 00:12:46	8175	Ecb:L Fire Extngr	1	ECBU	0	0	5
2020-12-14 00:12:46	8175	Ecb:L Fire Extngr	1	ECBU	0	0	6
2020-12-14 00:12:46	8176	Ecb:2.5A SPARE	1	ECBU	0	0	5
2020-12-14 00:12:46	8176	Ecb:2.5A SPARE	1	ECBU	0	0	6
2020-12-14 00:12:46	8177	Ecb:L GPS - 1	1	ECBU	0	0	5
2020-12-14 00:12:46	8177	Ecb:L GPS - 1	1	ECBU	0	0	6
2020-12-14 00:12:46	8178	Ecb:L ADF	1	ECBU	0	0	5
2020-12-14 00:12:46	8178	Ecb:L ADF	1	ECBU	0	0	6
2020-12-14 00:12:46	8179	Ecb:R Static Heat - B	1	ECBU	0	0	5
2020-12-14 00:12:46	8179	Ecb:R Static Heat - B	1	ECBU	0	0	6
2020-12-14 00:12:46	8180	Ecb:Voting Pitot Processor	1	ECBU	0	0	5
2020-12-14 00:12:46	8180	Ecb:Voting Pitot Processor	1	ECBU	0	0	6
	8181	Ecb:LH Start	1	ECBU	0	0	5

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:12:46							
2020-12-14 00:12:46	8181	Ecb:LH Start	1	ECBU	0	0	6
2020-12-14 00:12:46	8182	Ecb:MFD - 1	1	ECBU	0	0	5
2020-12-14 00:12:46	8182	Ecb:MFD - 1	1	ECBU	0	0	6
2020-12-14 00:12:46	8183	Ecb:DSU - 1	1	ECBU	0	0	5
2020-12-14 00:12:46	8183	Ecb:DSU - 1	1	ECBU	0	0	6
2020-12-14 00:12:46	8184	Ecb:Weather Radar	1	ECBU	0	0	5
2020-12-14 00:12:46	8184	Ecb:Weather Radar	1	ECBU	0	0	6
2020-12-14 00:12:46	8185	Ecb:EFB	1	ECBU	0	0	5
2020-12-14 00:12:46	8185	Ecb:EFB	1	ECBU	0	0	6
2020-12-14 00:12:46	8186	Ecb:Wing Inspection light	1	ECBU	0	0	5
2020-12-14 00:12:46	8186	Ecb:Wing Inspection light	1	ECBU	0	0	6
2020-12-14 00:12:46	8187	Ecb:L FADEC, ch A - 2	1	ECBU	0	0	5
2020-12-14 00:12:46	8187	Ecb:L FADEC, ch A - 2	1	ECBU	0	0	6
2020-12-14 00:12:46	8188	Ecb:R FADEC, ch A - 2	1	ECBU	0	0	5
2020-12-14 00:12:46	8188	Ecb:R FADEC, ch A - 2	1	ECBU	0	0	6
2020-12-14 00:12:46	8189	Ecb:Systems Battery Heat	1	ECBU	0	0	5
2020-12-14 00:12:46	8189	Ecb:Systems Battery Heat	1	ECBU	0	0	6
2020-12-14 00:12:46	8190	Ecb:R PFD - 1	1	ECBU	0	0	5
2020-12-14 00:12:46	8190	Ecb:R PFD - 1	1	ECBU	0	0	6
2020-12-14 00:12:46	8191	Ecb:Voting Pitot Heat	1	ECBU	0	0	5
2020-12-14 00:12:46	8191	Ecb:Voting Pitot Heat	1	ECBU	0	0	6
2020-12-14 00:12:46	8169	Ecb:Left AOA Processor	1	ECBU	0	0	5
2020-12-14 00:12:46	8169	Ecb:Left AOA Processor	1	ECBU	0	0	6
	8170	Ecb:TCAS II :SKYWATCH	1	ECBU	0	0	5

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:12:46							
2020-12-14 00:12:46	8170	Ecb:TCAS II :SKYWATCH	1	ECBU	0	0	6
2020-12-14 00:12:46	8171	Ecb:L CSP	1	ECBU	0	0	5
2020-12-14 00:12:46	8171	Ecb:L CSP	1	ECBU	0	0	6
2020-12-14 00:12:46	8172	Ecb:Auto O2	1	ECBU	0	0	5
2020-12-14 00:12:46	8172	Ecb:Auto O2	1	ECBU	0	0	6
2020-12-14 00:12:46	8173	Ecb:L AHRS - 1	1	ECBU	0	0	5
2020-12-14 00:12:46	8173	Ecb:L AHRS - 1	1	ECBU	0	0	6
2020-12-14 00:12:46	8174	Ecb:L ADC - 1	1	ECBU	0	0	5
2020-12-14 00:12:46	8174	Ecb:L ADC - 1	1	ECBU	0	0	6
2020-12-14 00:12:46	8175	Ecb:L Fire Extngr	1	ECBU	0	0	5
2020-12-14 00:12:46	8175	Ecb:L Fire Extngr	1	ECBU	0	0	6
2020-12-14 00:12:46	8176	Ecb:2.5A SPARE	1	ECBU	0	0	5
2020-12-14 00:12:46	8176	Ecb:2.5A SPARE	1	ECBU	0	0	6
2020-12-14 00:12:46	8177	Ecb:L GPS - 1	1	ECBU	0	0	5
2020-12-14 00:12:46	8177	Ecb:L GPS - 1	1	ECBU	0	0	6
2020-12-14 00:12:46	8178	Ecb:L ADF	1	ECBU	0	0	5
2020-12-14 00:12:46	8178	Ecb:L ADF	1	ECBU	0	0	6
2020-12-14 00:12:46	8179	Ecb:R Static Heat - B	1	ECBU	0	0	5
2020-12-14 00:12:46	8179	Ecb:R Static Heat - B	1	ECBU	0	0	6
2020-12-14 00:12:46	8180	Ecb:Voting Pitot Processor	1	ECBU	0	0	5
2020-12-14 00:12:46	8180	Ecb:Voting Pitot Processor	1	ECBU	0	0	6
2020-12-14 00:12:46	8181	Ecb:LH Start	1	ECBU	0	0	5
2020-12-14 00:12:46	8181	Ecb:LH Start	1	ECBU	0	0	6
	8182	Ecb:MFD - 1	1	ECBU	0	0	5

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:12:46							
2020-12-14 00:12:46	8182	Ecb:MFD - 1	1	ECBU	0	0	6
2020-12-14 00:12:46	8183	Ecb:DSU - 1	1	ECBU	0	0	5
2020-12-14 00:12:46	8183	Ecb:DSU - 1	1	ECBU	0	0	6
2020-12-14 00:12:46	8184	Ecb:Weather Radar	1	ECBU	0	0	5
2020-12-14 00:12:46	8184	Ecb:Weather Radar	1	ECBU	0	0	6
2020-12-14 00:12:46	8185	Ecb:EFB	1	ECBU	0	0	5
2020-12-14 00:12:46	8185	Ecb:EFB	1	ECBU	0	0	6
2020-12-14 00:12:46	8186	Ecb:Wing Inspection light	1	ECBU	0	0	5
2020-12-14 00:12:46	8186	Ecb:Wing Inspection light	1	ECBU	0	0	6
2020-12-14 00:12:46	8187	Ecb:L FADEC, ch A - 2	1	ECBU	0	0	5
2020-12-14 00:12:46	8187	Ecb:L FADEC, ch A - 2	1	ECBU	0	0	6
2020-12-14 00:12:46	8188	Ecb:R FADEC, ch A - 2	1	ECBU	0	0	5
2020-12-14 00:12:46	8188	Ecb:R FADEC, ch A - 2	1	ECBU	0	0	6
2020-12-14 00:12:46	8189	Ecb:Systems Battery Heat	1	ECBU	0	0	5
2020-12-14 00:12:46	8189	Ecb:Systems Battery Heat	1	ECBU	0	0	6
2020-12-14 00:12:46	8190	Ecb:R PFD - 1	1	ECBU	0	0	5
2020-12-14 00:12:46	8190	Ecb:R PFD - 1	1	ECBU	0	0	6
2020-12-14 00:12:46	8191	Ecb:Voting Pitot Heat	1	ECBU	0	0	5
2020-12-14 00:12:46	8191	Ecb:Voting Pitot Heat	1	ECBU	0	0	6
2020-12-14 00:12:46	8192	Ecb:R ACS - 1	1	ECBU	0	0	5
2020-12-14 00:12:46	8192	Ecb:R ACS - 1	1	ECBU	0	0	6
2020-12-14 00:12:46	8193	Ecb:Right AOA Processor	1	ECBU	0	0	5
2020-12-14 00:12:46	8193	Ecb:Right AOA Processor	1	ECBU	0	0	6
	8176	Ecb:2.5A SPARE	1	ECBU	0	0	5

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:12:46							
2020-12-14 00:12:46	8176	Ecb:2.5A SPARE	1	ECBU	0	0	6
2020-12-14 00:12:46	8194	Ecb:R CSP	1	ECBU	0	0	5
2020-12-14 00:12:46	8194	Ecb:R CSP	1	ECBU	0	0	6
2020-12-14 00:12:46	8176	Ecb:2.5A SPARE	1	ECBU	0	0	5
2020-12-14 00:12:46	8176	Ecb:2.5A SPARE	1	ECBU	0	0	6
2020-12-14 00:12:46	8195	Ecb:R AHRS - 1	1	ECBU	0	0	5
2020-12-14 00:12:46	8195	Ecb:R AHRS - 1	1	ECBU	0	0	6
2020-12-14 00:12:46	8199	Ecb:R GPS - 1	1	ECBU	0	0	5
2020-12-14 00:12:46	8199	Ecb:R GPS - 1	1	ECBU	0	0	6
2020-12-14 00:12:46	8200	Ecb:L ACS - 2	1	ECBU	0	0	5
2020-12-14 00:12:46	8200	Ecb:L ACS - 2	1	ECBU	0	0	6
2020-12-14 00:12:46	8201	Ecb:L FADEC, ch A - 1	1	ECBU	0	0	5
2020-12-14 00:12:46	8201	Ecb:L FADEC, ch A - 1	1	ECBU	0	0	6
2020-12-14 00:12:46	8203	Ecb:R FADEC, ch A - 1	1	ECBU	0	0	5
2020-12-14 00:12:46	8203	Ecb:R FADEC, ch A - 1	1	ECBU	0	0	6
2020-12-14 00:12:46	8204	Ecb:R FADEC, ch B - 1	1	ECBU	0	0	5
2020-12-14 00:12:46	8204	Ecb:R FADEC, ch B - 1	1	ECBU	0	0	6
2020-12-14 00:12:46	8209	Ecb:Start Battery Heat	1	ECBU	0	0	5
2020-12-14 00:12:46	8209	Ecb:Start Battery Heat	1	ECBU	0	0	6
2020-12-14 00:12:46	8176	Ecb:2.5A SPARE	1	ECBU	0	0	5
2020-12-14 00:12:46	8176	Ecb:2.5A SPARE	1	ECBU	0	0	6
2020-12-14 00:12:46	8218	Ecb:L PRSOV	1	ECBU	0	0	5
2020-12-14 00:12:46	8218	Ecb:L PRSOV	1	ECBU	0	0	6
	8176	Ecb:2.5A SPARE	1	ECBU	0	0	5

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:12:46							
2020-12-14 00:12:46	8176	Ecb:2.5A SPARE	1	ECBU	0	0	6
2020-12-14 00:12:46	8222	Ecb:L Firewall SOV - Close	1	ECBU	0	0	5
2020-12-14 00:12:46	8222	Ecb:L Firewall SOV - Close	1	ECBU	0	0	6
2020-12-14 00:12:46	8229	Ecb:Tail Anti-Collision Lt	1	ECBU	0	0	5
2020-12-14 00:12:46	8229	Ecb:Tail Anti-Collision Lt	1	ECBU	0	0	6
2020-12-14 00:12:46	8230	Ecb:L Taxi Light	1	ECBU	0	0	5
2020-12-14 00:12:46	8230	Ecb:L Taxi Light	1	ECBU	0	0	6
2020-12-14 00:12:46	8209	Ecb:Start Battery Heat	1	ECBU	0	0	5
2020-12-14 00:12:46	8209	Ecb:Start Battery Heat	1	ECBU	0	0	6
2020-12-14 00:12:46	8210	Ecb:L Flow Control SOV A1	1	ECBU	0	0	5
2020-12-14 00:12:46	8210	Ecb:L Flow Control SOV A1	1	ECBU	0	0	6
2020-12-14 00:12:46	8212	Ecb:R ISS - 2	1	ECBU	0	0	5
2020-12-14 00:12:46	8212	Ecb:R ISS - 2	1	ECBU	0	0	6
2020-12-14 00:12:46	8232	Ecb:Inboard De-ice - 1	1	ECBU	0	0	5
2020-12-14 00:12:46	8232	Ecb:Inboard De-ice - 1	1	ECBU	0	0	6
2020-12-14 00:12:46	8218	Ecb:L PRSOV	1	ECBU	0	0	5
2020-12-14 00:12:46	8218	Ecb:L PRSOV	1	ECBU	0	0	6
2020-12-14 00:12:46	8219	Ecb:XM Weather	1	ECBU	0	0	5
2020-12-14 00:12:46	8219	Ecb:XM Weather	1	ECBU	0	0	6
2020-12-14 00:12:46	8225	Ecb:Aft Evap Fan - Med	1	ECBU	0	0	5
2020-12-14 00:12:46	8225	Ecb:Aft Evap Fan - Med	1	ECBU	0	0	6
2020-12-14 00:12:46	8234	Ecb:Condenser fans	1	ECBU	0	0	5
2020-12-14 00:12:46	8234	Ecb:Condenser fans	1	ECBU	0	0	6
	8236	Ecb:Aft Evap Fan - High	1	ECBU	0	0	5

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:12:46							
2020-12-14 00:12:46	8236	Ecb:Aft Evap Fan - High	1	ECBU	0	0	6
2020-12-14 00:12:46	8239	Ecb:Nose Landing Gear	1	ECBU	0	0	5
2020-12-14 00:12:46	8239	Ecb:Nose Landing Gear	1	ECBU	0	0	6
2020-12-14 00:12:47	8197	Ecb:R Fire Extngr	1	ECBU	0	0	6
2020-12-14 00:12:47	8196	Ecb:R ADC - 1	1	ECBU	0	0	5
2020-12-14 00:12:47	8196	Ecb:R ADC - 1	1	ECBU	0	0	6
2020-12-14 00:12:47	8198	Ecb:L Static Heat - B	1	ECBU	0	0	5
2020-12-14 00:12:47	8198	Ecb:L Static Heat - B	1	ECBU	0	0	6
2020-12-14 00:12:47	1082	ACS_DO_EPC_CONTROL_FAIL	1	L-ACS	0	0	0
2020-12-14 00:12:47	1082	ACS_DO_EPC_CONTROL_FAIL	0	L-ACS	0	0	0
2020-12-14 00:12:47	8202	Ecb:L FADEC, ch B - 1	1	ECBU	0	0	5
2020-12-14 00:12:47	8202	Ecb:L FADEC, ch B - 1	1	ECBU	0	0	6
2020-12-14 00:12:47	8205	Ecb:L Pitot:AOA Heat	1	ECBU	0	0	5
2020-12-14 00:12:50	8205	Ecb:L Pitot:AOA Heat	1	ECBU	0	0	6
2020-12-14 00:12:50	8207	Ecb:L ISS - 2	1	ECBU	0	0	5
2020-12-14 00:12:51	8207	Ecb:L ISS - 2	1	ECBU	0	0	6
2020-12-14 00:12:51	8176	Ecb:2.5A SPARE	1	ECBU	0	0	5
2020-12-14 00:12:53	8176	Ecb:2.5A SPARE	1	ECBU	0	0	6
2020-12-14 00:12:53	8208	Ecb:Third AHRS	1	ECBU	0	0	5
2020-12-14 00:12:54	8208	Ecb:Third AHRS	1	ECBU	0	0	6
2020-12-14 00:12:54	8210	Ecb:L Flow Control SOV A1	1	ECBU	0	0	5
2020-12-14 00:12:57	8210	Ecb:L Flow Control SOV A1	1	ECBU	0	0	6
2020-12-14 00:12:57	8211	Ecb:L Flow Control SOV B1	1	ECBU	0	0	5
	8211	Ecb:L Flow Control SOV B1	1	ECBU	0	0	6

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:12:58							
2020-12-14 00:12:58	8212	Ecb:R ISS - 2	1	ECBU	0	0	5
2020-12-14 00:12:59	8212	Ecb:R ISS - 2	1	ECBU	0	0	6
2020-12-14 00:12:59	8213	Ecb:Outboard De-ice - 1	1	ECBU	0	0	5
2020-12-14 00:13:01	8213	Ecb:Outboard De-ice - 1	1	ECBU	0	0	6
2020-12-14 00:13:01	1082	ACS_DO_EPC_CONTROL_FAIL	1	L-ACS	0	0	0
2020-12-14 00:13:01	1082	ACS_DO_EPC_CONTROL_FAIL	0	L-ACS	0	0	0
2020-12-14 00:13:02	8214	Ecb:TAWS	1	ECBU	0	0	5
2020-12-14 00:13:02	8214	Ecb:TAWS	1	ECBU	0	0	6
2020-12-14 00:13:02	8215	Ecb:Cabin alt switch:dump	1	ECBU	0	0	5
2020-12-14 00:13:04	8215	Ecb:Cabin alt switch:dump	1	ECBU	0	0	6
2020-12-14 00:13:04	8216	Ecb:Radar Altimeter	1	ECBU	0	0	5
2020-12-14 00:13:05	8216	Ecb:Radar Altimeter	1	ECBU	0	0	6
2020-12-14 00:13:05	8217	Ecb:LH Gen ON	1	ECBU	0	0	5
2020-12-14 00:13:06	8217	Ecb:LH Gen ON	1	ECBU	0	0	6
2020-12-14 00:13:06	8219	Ecb:XM Weather	1	ECBU	0	0	5
2020-12-14 00:13:09	8219	Ecb:XM Weather	1	ECBU	0	0	6
2020-12-14 00:13:09	8220	Ecb:Logo Lights	1	ECBU	0	0	5
2020-12-14 00:13:12	8220	Ecb:Logo Lights	1	ECBU	0	0	6
2020-12-14 00:13:12	8221	Ecb:L Firewall SOV - Open	1	ECBU	0	0	5
2020-12-14 00:13:13	8221	Ecb:L Firewall SOV - Open	1	ECBU	0	0	6
2020-12-14 00:13:13	8223	Ecb:L Ignition	1	ECBU	0	0	5
2020-12-14 00:13:14	8223	Ecb:L Ignition	1	ECBU	0	0	6
2020-12-14 00:13:14	8224	Ecb:L:R Segregation Valve	1	ECBU	0	0	5
	8224	Ecb:L:R Segregation Valve	1	ECBU	0	0	6

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:13:16							
2020-12-14 00:13:16	8225	Ecb:Aft Evap Fan - Med	1	ECBU	0	0	5
2020-12-14 00:13:17	8225	Ecb:Aft Evap Fan - Med	1	ECBU	0	0	6
2020-12-14 00:13:17	8226	Ecb:Aft Evap Fan - Low	1	ECBU	0	0	5
2020-12-14 00:13:18	8226	Ecb:Aft Evap Fan - Low	1	ECBU	0	0	6
2020-12-14 00:13:18	8227	Ecb:L Anti-Collision Lt	1	ECBU	0	0	5
2020-12-14 00:13:20	8227	Ecb:L Anti-Collision Lt	1	ECBU	0	0	6
2020-12-14 00:13:20	8228	Ecb:R Anti-Collision Lt	1	ECBU	0	0	5
2020-12-14 00:13:21	8228	Ecb:R Anti-Collision Lt	1	ECBU	0	0	6
2020-12-14 00:13:21	8231	Ecb:L Engine Start Pump	1	ECBU	0	0	5
2020-12-14 00:13:24	8231	Ecb:L Engine Start Pump	1	ECBU	0	0	6
2020-12-14 00:13:24	8211	Ecb:L Flow Control SOV B1	1	ECBU	0	0	5
2020-12-14 00:13:29	8211	Ecb:L Flow Control SOV B1	1	ECBU	0	0	6
2020-12-14 00:13:29	8213	Ecb:Outboard De-ice - 1	1	ECBU	0	0	5
2020-12-14 00:13:32	8213	Ecb:Outboard De-ice - 1	1	ECBU	0	0	6
2020-12-14 00:13:32	8214	Ecb:TAWS	1	ECBU	0	0	5
2020-12-14 00:13:33	8214	Ecb:TAWS	1	ECBU	0	0	6
2020-12-14 00:13:33	8215	Ecb:Cabin alt switch:dump	1	ECBU	0	0	5
2020-12-14 00:13:35	8215	Ecb:Cabin alt switch:dump	1	ECBU	0	0	6
2020-12-14 00:13:35	8216	Ecb:Radar Altimeter	1	ECBU	0	0	5
2020-12-14 00:13:36	8216	Ecb:Radar Altimeter	1	ECBU	0	0	6
2020-12-14 00:13:36	8176	Ecb:2.5A SPARE	1	ECBU	0	0	5
2020-12-14 00:13:37	8176	Ecb:2.5A SPARE	1	ECBU	0	0	6
2020-12-14 00:13:37	8217	Ecb:LH Gen ON	1	ECBU	0	0	5
	8217	Ecb:LH Gen ON	1	ECBU	0	0	6

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:13:37							
2020-12-14 00:13:37	8176	Ecb:2.5A SPARE	1	ECBU	0	0	5
2020-12-14 00:13:41	8176	Ecb:2.5A SPARE	1	ECBU	0	0	6
2020-12-14 00:13:41	8220	Ecb:Logo Lights	1	ECBU	0	0	5
2020-12-14 00:13:43	8220	Ecb:Logo Lights	1	ECBU	0	0	6
2020-12-14 00:13:43	8221	Ecb:L Firewall SOV - Open	1	ECBU	0	0	5
2020-12-14 00:13:44	8221	Ecb:L Firewall SOV - Open	1	ECBU	0	0	6
2020-12-14 00:13:44	8233	Ecb:L Firewall SOV - Close	1	ECBU	0	0	5
2020-12-14 00:13:45	8233	Ecb:L Firewall SOV - Close	1	ECBU	0	0	6
2020-12-14 00:13:45	8223	Ecb:L Ignition	1	ECBU	0	0	5
2020-12-14 00:13:46	8223	Ecb:L Ignition	1	ECBU	0	0	6
2020-12-14 00:13:46	8224	Ecb:L:R Segregation Valve	1	ECBU	0	0	5
2020-12-14 00:13:47	8224	Ecb:L:R Segregation Valve	1	ECBU	0	0	6
2020-12-14 00:13:47	8226	Ecb:Aft Evap Fan - Low	1	ECBU	0	0	5
2020-12-14 00:13:50	8226	Ecb:Aft Evap Fan - Low	1	ECBU	0	0	6
2020-12-14 00:13:50	8227	Ecb:L Anti-Collision Lt	1	ECBU	0	0	5
2020-12-14 00:13:51	8227	Ecb:L Anti-Collision Lt	1	ECBU	0	0	6
2020-12-14 00:13:51	8228	Ecb:R Anti-Collision Lt	1	ECBU	0	0	5
2020-12-14 00:13:52	8228	Ecb:R Anti-Collision Lt	1	ECBU	0	0	6
2020-12-14 00:13:52	8229	Ecb:Tail Anti-Collision Lt	1	ECBU	0	0	5
2020-12-14 00:13:54	8229	Ecb:Tail Anti-Collision Lt	1	ECBU	0	0	6
2020-12-14 00:13:54	8230	Ecb:L Taxi Light	1	ECBU	0	0	5
2020-12-14 00:13:54	8230	Ecb:L Taxi Light	1	ECBU	0	0	6
2020-12-14 00:13:54	1082	ACS_DO_EPC_CONTROL_FAIL	1	L-ACS	0	0	0
	8231	Ecb:L Engine Start Pump	1	ECBU	0	0	5

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:13:55							
2020-12-14 00:13:55	8231	Ecb:L Engine Start Pump	1	ECBU	0	0	6
2020-12-14 00:13:55	1082	ACS_DO_EPC_CONTROL_FAIL	0	L-ACS	0	0	0
2020-12-14 00:13:56	8235	Ecb:L Landing Light	1	ECBU	0	0	5
2020-12-14 00:13:58	8235	Ecb:L Landing Light	1	ECBU	0	0	6
2020-12-14 00:13:58	8238	Ecb:R Main Landing Gear	1	ECBU	0	0	5
2020-12-14 00:14:02	8238	Ecb:R Main Landing Gear	1	ECBU	0	0	6
2020-12-14 00:14:02	8240	Ecb:25A SPARE	1	ECBU	0	0	5
2020-12-14 00:14:03	8240	Ecb:25A SPARE	1	ECBU	0	0	6
2020-12-14 00:14:03	8240	Ecb:25A SPARE	1	ECBU	0	0	5
2020-12-14 00:14:04	8240	Ecb:25A SPARE	1	ECBU	0	0	6
2020-12-14 00:14:04	8241	Ecb:30A SPARE	1	ECBU	0	0	5
2020-12-14 00:14:06	8241	Ecb:30A SPARE	1	ECBU	0	0	6
2020-12-14 00:14:08	1082	ACS_DO_EPC_CONTROL_FAIL	1	L-ACS	0	0	0
2020-12-14 00:14:16	1082	ACS_DO_EPC_CONTROL_FAIL	0	L-ACS	0	0	0
2020-12-14 00:14:16	133	FADEC_L_MANUAL_TAT_SELECTED	1	R-ACS	0	0	0
2020-12-14 00:14:31	134	FADEC_R_MANUAL_TAT_SELECTED	1	R-ACS	0	0	0
2020-12-14 00:14:31	134	FADEC_R_MANUAL_TAT_SELECTED	1	L-ACS	0	0	0
2020-12-14 00:14:31	133	FADEC_L_MANUAL_TAT_SELECTED	1	L-ACS	0	0	0
2020-12-14 00:14:31	1082	ACS_DO_EPC_CONTROL_FAIL	1	L-ACS	0	0	0
2020-12-14 00:14:36	1082	ACS_DO_EPC_CONTROL_FAIL	0	L-ACS	0	0	0
2020-12-14 00:14:37	1082	ACS_DO_EPC_CONTROL_FAIL	1	L-ACS	0	0	0
2020-12-14 00:14:57	1082	ACS_DO_EPC_CONTROL_FAIL	0	L-ACS	0	0	0
2020-12-14 00:14:58	2042	R_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
	2042	R_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:14:59							
2020-12-14 00:14:59	2042	R_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:15:04	2042	R_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:15:04	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:15:30	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:15:30	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:15:32	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:15:32	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:15:35	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:15:35	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:15:37	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:15:37	1082	ACS_DO_EPC_CONTROL_FAIL	1	R-ACS	0	0	0
2020-12-14 00:15:44	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:15:44	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:15:44	1082	ACS_DO_EPC_CONTROL_FAIL	0	R-ACS	0	0	0
2020-12-14 00:15:44	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:15:44	1082	ACS_DO_EPC_CONTROL_FAIL	1	L-ACS	0	0	0
2020-12-14 00:15:48	1082	ACS_DO_EPC_CONTROL_FAIL	0	L-ACS	0	0	0
2020-12-14 00:15:48	1082	ACS_DO_EPC_CONTROL_FAIL	1	L-ACS	0	0	0
2020-12-14 00:16:08	1082	ACS_DO_EPC_CONTROL_FAIL	0	L-ACS	0	0	0
2020-12-14 00:16:09	1082	ACS_DO_EPC_CONTROL_FAIL	1	R-ACS	0	0	0
2020-12-14 00:16:34	1082	ACS_DO_EPC_CONTROL_FAIL	0	R-ACS	0	0	0
2020-12-14 00:16:35	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:16:51	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
	1082	ACS_DO_EPC_CONTROL_FAIL	1	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:16:51							
2020-12-14 00:16:58	1082	ACS_DO_EPC_CONTROL_FAIL	0	L-ACS	0	0	0
2020-12-14 00:16:59	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:17:10	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:17:10	1082	ACS_DO_EPC_CONTROL_FAIL	1	L-ACS	0	0	0
2020-12-14 00:17:19	1082	ACS_DO_EPC_CONTROL_FAIL	0	L-ACS	0	0	0
2020-12-14 00:17:20	1082	ACS_DO_EPC_CONTROL_FAIL	1	R-ACS	0	0	0
2020-12-14 00:17:24	1082	ACS_DO_EPC_CONTROL_FAIL	0	R-ACS	0	0	0
2020-12-14 00:17:25	1082	ACS_DO_EPC_CONTROL_FAIL	1	L-ACS	0	0	0
2020-12-14 00:18:09	1082	ACS_DO_EPC_CONTROL_FAIL	0	L-ACS	0	0	0
2020-12-14 00:18:09	1859	STROBE_LIGHT_SW_ON	1	L-ACS	0	0	0
2020-12-14 00:18:43	1860	BEACON_LIGHT_SW_ON	1	L-ACS	0	0	0
2020-12-14 00:18:43	1860	BEACON_LIGHT_SW_ON	1	R-ACS	0	0	0
2020-12-14 00:18:43	1082	ACS_DO_EPC_CONTROL_FAIL	1	R-ACS	0	0	0
2020-12-14 00:18:43	1859	STROBE_LIGHT_SW_ON	0	L-ACS	0	0	0
2020-12-14 00:18:43	1082	ACS_DO_EPC_CONTROL_FAIL	0	R-ACS	0	0	0
2020-12-14 00:18:44	1082	ACS_DO_EPC_CONTROL_FAIL	1	L-ACS	0	0	0
2020-12-14 00:18:58	1082	ACS_DO_EPC_CONTROL_FAIL	0	L-ACS	0	0	0
2020-12-14 00:18:59	540	FUEL_AUTO_LAT_CG_TRANSFER_DISABLE	0	R-ACS	0	0	0
2020-12-14 00:19:07	540	FUEL_AUTO_LAT_CG_TRANSFER_DISABLE	0	L-ACS	0	0	0
2020-12-14 00:19:08	550	L_ESP_ON	1	L-ACS	0	0	0
2020-12-14 00:19:08	550	L_ESP_ON	1	R-ACS	0	0	0
2020-12-14 00:19:08	965	ACS_AI_BIT_CONDO_OG1_WRAP_FAIL	0	L-ACS	1	1	0
2020-12-14 00:19:10	177	EPDS_SYS_BATT_DISCHARGING	0	L-ACS	0	0	0
	178	EPDS_START_BATT_DISCHARGING	0	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:19:11							
2020-12-14 00:19:11	177	EPDS_SYS_BATT_DISCHARGING	0	R-ACS	0	0	0
2020-12-14 00:19:11	178	EPDS_START_BATT_DISCHARGING	0	R-ACS	0	0	0
2020-12-14 00:19:11	730	MASTER_CAUTION_DISABLE	0	R-ACS	1	1	0
2020-12-14 00:19:15	730	MASTER_CAUTION_DISABLE	0	L-ACS	1	1	0
2020-12-14 00:19:15	1082	ACS_DO_EPC_CONTROL_FAIL	1	L-ACS	0	0	0
2020-12-14 00:19:27	1082	ACS_DO_EPC_CONTROL_FAIL	0	L-ACS	0	0	0
2020-12-14 00:19:28	550	L_ESP_ON	0	L-ACS	0	0	0
2020-12-14 00:19:38	550	L_ESP_ON	0	R-ACS	0	0	0
2020-12-14 00:19:38	680	DEICE_L_SUPPLY_PRESS_LOW	1	L-ACS	0	0	0
2020-12-14 00:19:39	680	DEICE_L_SUPPLY_PRESS_LOW	1	R-ACS	0	0	0
2020-12-14 00:19:39	1373	LEFT_BLEED_AIR_AVAIL	1	L-ACS	0	0	0
2020-12-14 00:19:40	1373	LEFT_BLEED_AIR_AVAIL	1	R-ACS	0	0	0
2020-12-14 00:19:40	180	L_GEN_OFFLINE	1	L-ACS	0	0	0
2020-12-14 00:19:43	180	L_GEN_OFFLINE	1	R-ACS	0	0	0
2020-12-14 00:19:43	180	L_GEN_OFFLINE	0	L-ACS	0	0	0
2020-12-14 00:19:44	155	EPDS_SINGLE_GEN_LOAD_SHED	1	R-ACS	0	0	0
2020-12-14 00:19:44	180	L_GEN_OFFLINE	0	R-ACS	0	0	0
2020-12-14 00:19:44	155	EPDS_SINGLE_GEN_LOAD_SHED	1	L-ACS	0	0	0
2020-12-14 00:19:44	1078	ACS_DO_L_GCU_RESET_FAIL	1	L-ACS	0	0	0
2020-12-14 00:19:45	8216	Ecb:Radar Altimeter	1	ECBU	0	0	4
2020-12-14 00:19:45	8223	Ecb:L Ignition	1	ECBU	0	0	4
2020-12-14 00:19:45	8227	Ecb:L Anti-Collision Lt	1	ECBU	0	0	4
2020-12-14 00:19:45	8237	Ecb:L Main Landing Gear	1	ECBU	0	0	4
	1078	ACS_DO_L_GCU_RESET_FAIL	0	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:19:45							
2020-12-14 00:19:46	1077	ACS_DO_R_ENGINE_STOP_FAIL	1	L-ACS	0	0	0
2020-12-14 00:19:54	1077	ACS_DO_R_ENGINE_STOP_FAIL	1	R-ACS	0	0	0
2020-12-14 00:19:54	551	R_ESP_ON	1	L-ACS	0	0	0
2020-12-14 00:19:54	551	R_ESP_ON	1	R-ACS	0	0	0
2020-12-14 00:19:54	965	ACS_AI_BIT_CONDO_OG1_WRAP_FAIL	0	R-ACS	1	1	0
2020-12-14 00:19:57	700	L_WINDSHIELD_HEAT_OFF	0	R-ACS	0	0	0
2020-12-14 00:20:24	701	R_WINDSHIELD_HEAT_OFF	0	R-ACS	0	0	0
2020-12-14 00:20:24	702	* L_WINDSHIELD_HEAT_ON	1	R-ACS	0	0	0
2020-12-14 00:20:24	703	* R_WINDSHIELD_HEAT_ON	1	R-ACS	0	0	0
2020-12-14 00:20:24	700	L_WINDSHIELD_HEAT_OFF	0	L-ACS	0	0	0
2020-12-14 00:20:25	701	R_WINDSHIELD_HEAT_OFF	0	L-ACS	0	0	0
2020-12-14 00:20:25	702	* L_WINDSHIELD_HEAT_ON	1	L-ACS	0	0	0
2020-12-14 00:20:25	703	* R_WINDSHIELD_HEAT_ON	1	L-ACS	0	0	0
2020-12-14 00:20:25	551	R_ESP_ON	0	L-ACS	0	0	0
2020-12-14 00:20:25	551	R_ESP_ON	0	R-ACS	0	0	0
2020-12-14 00:20:25	681	DEICE_R_SUPPLY_PRESS_LOW	1	R-ACS	0	0	0
2020-12-14 00:20:25	681	DEICE_R_SUPPLY_PRESS_LOW	1	L-ACS	0	0	0
2020-12-14 00:20:25	1079	ACS_DO_R_GCU_RESET_FAIL	1	R-ACS	0	0	0
2020-12-14 00:20:25	1374	RIGHT_BLEED_AIR_AVAIL	1	L-ACS	0	0	0
2020-12-14 00:20:25	1374	RIGHT_BLEED_AIR_AVAIL	1	R-ACS	0	0	0
2020-12-14 00:20:26	1079	ACS_DO_R_GCU_RESET_FAIL	0	R-ACS	0	0	0
2020-12-14 00:20:26	155	EPDS_SINGLE_GEN_LOAD_SHED	0	R-ACS	0	0	0
2020-12-14 00:20:27	155	EPDS_SINGLE_GEN_LOAD_SHED	0	L-ACS	0	0	0
	700	L_WINDSHIELD_HEAT_OFF	1	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:20:27							
2020-12-14 00:20:39	701	R_WINDSHIELD_HEAT_OFF	1	L-ACS	0	0	0
2020-12-14 00:20:39	702	* L_WINDSHIELD_HEAT_ON	0	L-ACS	0	0	0
2020-12-14 00:20:39	703	* R_WINDSHIELD_HEAT_ON	0	L-ACS	0	0	0
2020-12-14 00:20:39	700	L_WINDSHIELD_HEAT_OFF	1	R-ACS	0	0	0
2020-12-14 00:20:39	701	R_WINDSHIELD_HEAT_OFF	1	R-ACS	0	0	0
2020-12-14 00:20:39	702	* L_WINDSHIELD_HEAT_ON	0	R-ACS	0	0	0
2020-12-14 00:20:39	703	* R_WINDSHIELD_HEAT_ON	0	R-ACS	0	0	0
2020-12-14 00:20:39	753	TAKEOFF_CONFIG_OK	1	R-ACS	0	0	0
2020-12-14 00:20:43	753	TAKEOFF_CONFIG_OK	1	L-ACS	0	0	0
2020-12-14 00:20:43	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:20:59	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:20:59	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:21:04	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:21:04	680	DEICE_L_SUPPLY_PRESS_LOW	0	L-ACS	0	0	0
2020-12-14 00:21:08	680	DEICE_L_SUPPLY_PRESS_LOW	0	R-ACS	0	0	0
2020-12-14 00:21:08	681	DEICE_R_SUPPLY_PRESS_LOW	0	R-ACS	0	0	0
2020-12-14 00:21:08	681	DEICE_R_SUPPLY_PRESS_LOW	0	L-ACS	0	0	0
2020-12-14 00:21:08	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:21:09	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:21:10	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:21:13	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:21:13	680	DEICE_L_SUPPLY_PRESS_LOW	1	L-ACS	0	0	0
2020-12-14 00:21:55	681	DEICE_R_SUPPLY_PRESS_LOW	1	L-ACS	0	0	0
	680	DEICE_L_SUPPLY_PRESS_LOW	1	R-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:21:55							
2020-12-14 00:21:55	681	DEICE_R_SUPPLY_PRESS_LOW	1	R-ACS	0	0	0
2020-12-14 00:21:55	680	DEICE_L_SUPPLY_PRESS_LOW	0	L-ACS	0	0	0
2020-12-14 00:22:20	680	DEICE_L_SUPPLY_PRESS_LOW	0	R-ACS	0	0	0
2020-12-14 00:22:20	681	DEICE_R_SUPPLY_PRESS_LOW	0	L-ACS	0	0	0
2020-12-14 00:22:21	681	DEICE_R_SUPPLY_PRESS_LOW	0	R-ACS	0	0	0
2020-12-14 00:22:21	680	DEICE_L_SUPPLY_PRESS_LOW	1	R-ACS	0	0	0
2020-12-14 00:22:46	681	DEICE_R_SUPPLY_PRESS_LOW	1	R-ACS	0	0	0
2020-12-14 00:22:46	680	DEICE_L_SUPPLY_PRESS_LOW	1	L-ACS	0	0	0
2020-12-14 00:22:46	681	DEICE_R_SUPPLY_PRESS_LOW	1	L-ACS	0	0	0
2020-12-14 00:22:46	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:23:11	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:23:12	680	DEICE_L_SUPPLY_PRESS_LOW	0	L-ACS	0	0	0
2020-12-14 00:23:15	680	DEICE_L_SUPPLY_PRESS_LOW	0	R-ACS	0	0	0
2020-12-14 00:23:15	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:23:15	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:23:15	681	DEICE_R_SUPPLY_PRESS_LOW	0	R-ACS	0	0	0
2020-12-14 00:23:16	681	DEICE_R_SUPPLY_PRESS_LOW	0	L-ACS	0	0	0
2020-12-14 00:23:16	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:23:20	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:23:20	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:23:23	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:23:23	680	DEICE_L_SUPPLY_PRESS_LOW	1	L-ACS	0	0	0
2020-12-14 00:23:33	681	DEICE_R_SUPPLY_PRESS_LOW	1	L-ACS	0	0	0
	680	DEICE_L_SUPPLY_PRESS_LOW	1	R-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:23:33							
2020-12-14 00:23:33	681	DEICE_R_SUPPLY_PRESS_LOW	1	R-ACS	0	0	0
2020-12-14 00:23:33	753	TAKEOFF_CONFIG_OK	0	R-ACS	0	0	0
2020-12-14 00:23:43	753	TAKEOFF_CONFIG_OK	0	L-ACS	0	0	0
2020-12-14 00:23:43	540	FUEL_AUTO_LAT_CG_TRANSFER_DISABLE	1	L-ACS	0	0	0
2020-12-14 00:23:43	540	FUEL_AUTO_LAT_CG_TRANSFER_DISABLE	1	R-ACS	0	0	0
2020-12-14 00:23:43	680	DEICE_L_SUPPLY_PRESS_LOW	0	L-ACS	0	0	0
2020-12-14 00:23:43	681	DEICE_R_SUPPLY_PRESS_LOW	0	L-ACS	0	0	0
2020-12-14 00:23:43	680	DEICE_L_SUPPLY_PRESS_LOW	0	R-ACS	0	0	0
2020-12-14 00:23:44	681	DEICE_R_SUPPLY_PRESS_LOW	0	R-ACS	0	0	0
2020-12-14 00:23:44	136	FADEC_R_CONTINUOUS_RATING_THERMALLY_LIMITED	1	L-ACS	0	0	0
2020-12-14 00:23:44	136	FADEC_R_CONTINUOUS_RATING_THERMALLY_LIMITED	1	R-ACS	0	0	0
2020-12-14 00:23:44	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	1	L-ACS	0	0	0
2020-12-14 00:23:44	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	1	R-ACS	0	0	0
2020-12-14 00:23:44	136	FADEC_R_CONTINUOUS_RATING_THERMALLY_LIMITED	0	R-ACS	0	0	0
2020-12-14 00:23:45	136	FADEC_R_CONTINUOUS_RATING_THERMALLY_LIMITED	0	L-ACS	0	0	0
2020-12-14 00:23:45	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	0	L-ACS	0	0	0
2020-12-14 00:23:45	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	0	R-ACS	0	0	0
2020-12-14 00:23:45	540	FUEL_AUTO_LAT_CG_TRANSFER_DISABLE	0	R-ACS	0	0	0
2020-12-14 00:23:45	540	FUEL_AUTO_LAT_CG_TRANSFER_DISABLE	0	L-ACS	0	0	0
2020-12-14 00:23:46	76	R_ENG_OIL_PRESS_HIGH_CAUTION	1	R-ACS	0	0	0
2020-12-14 00:23:47	76	R_ENG_OIL_PRESS_HIGH_CAUTION	1	L-ACS	0	0	0
2020-12-14 00:23:47	87	FADEC_L_FADEC_MINOR_INDICATION	1	L-ACS	1	1	0
2020-12-14 00:23:48	87	FADEC_L_FADEC_MINOR_INDICATION	1	R-ACS	1	1	0
	87	FADEC_L_FADEC_MINOR_INDICATION	0	L-ACS	1	1	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:23:48							
2020-12-14 00:23:48	87	FADEC_L_FADEC_MINOR_INDICATION	0	R-ACS	1	1	0
2020-12-14 00:23:48	1857	TAXI_RECOG_LIGHT_SW_ON	1	R-ACS	0	0	0
2020-12-14 00:23:56	1858	LANDING_LIGHT_SW_ON	1	R-ACS	0	0	0
2020-12-14 00:23:56	1858	LANDING_LIGHT_SW_ON	1	L-ACS	0	0	0
2020-12-14 00:23:56	1857	TAXI_RECOG_LIGHT_SW_ON	1	L-ACS	0	0	0
2020-12-14 00:24:01	1371	ACS_BAD_NVM_WRITE_VERIFY_FAILURE	1	L-ACS	1	1	0
2020-12-14 00:24:03	606	* IN_AIR	1	R-ACS	0	0	0
2020-12-14 00:24:03	1371	ACS_BAD_NVM_WRITE_VERIFY_FAILURE	1	R-ACS	0	0	0
2020-12-14 00:24:03	606	* IN_AIR	1	L-ACS	0	0	0
2020-12-14 00:24:03	1075	ACS_DO_IN_AIR_FAIL	0	R-ACS	0	0	0
2020-12-14 00:24:03	1075	ACS_DO_IN_AIR_FAIL	0	L-ACS	0	0	0
2020-12-14 00:24:03	1984	* L_PFD_ACTIVE_TRANSPONDER_ALT_MODE	0	L-ACS	0	0	0
2020-12-14 00:24:03	2049	R_PFD_ACTIVE_TRANSPONDER_ALT_MODE	0	R-ACS	0	0	0
2020-12-14 00:24:04	1984	* L_PFD_ACTIVE_TRANSPONDER_ALT_MODE	0	R-ACS	0	0	0
2020-12-14 00:24:04	2049	R_PFD_ACTIVE_TRANSPONDER_ALT_MODE	0	L-ACS	0	0	0
2020-12-14 00:24:04	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	1	L-ACS	0	0	0
2020-12-14 00:24:16	136	FADEC_R_CONTINUOUS_RATING_THERMALLY_LIMITED	1	L-ACS	0	0	0
2020-12-14 00:24:16	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	1	R-ACS	0	0	0
2020-12-14 00:24:16	136	FADEC_R_CONTINUOUS_RATING_THERMALLY_LIMITED	1	R-ACS	0	0	0
2020-12-14 00:24:16	76	R_ENG_OIL_PRESS_HIGH_CAUTION	0	R-ACS	0	0	0
2020-12-14 00:24:17	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	0	L-ACS	0	0	0
2020-12-14 00:24:17	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	0	R-ACS	0	0	0
2020-12-14 00:24:17	136	FADEC_R_CONTINUOUS_RATING_THERMALLY_LIMITED	0	L-ACS	0	0	0
	136	FADEC_R_CONTINUOUS_RATING_THERMALLY_LIMITED	0	R-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:24:17							
2020-12-14 00:24:18	133	FADEC_L_MANUAL_TAT_SELECTED	0	L-ACS	0	0	0
2020-12-14 00:24:23	134	FADEC_R_MANUAL_TAT_SELECTED	0	L-ACS	0	0	0
2020-12-14 00:24:23	133	FADEC_L_MANUAL_TAT_SELECTED	0	R-ACS	0	0	0
2020-12-14 00:24:23	134	FADEC_R_MANUAL_TAT_SELECTED	0	R-ACS	0	0	0
2020-12-14 00:24:30	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:24:33	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:24:33	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:24:34	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:24:34	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:24:36	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:24:36	733	PITCH_TRIM_IN_MOTION	1	L-ACS	0	0	0
2020-12-14 00:24:38	733	PITCH_TRIM_IN_MOTION	1	R-ACS	0	0	0
2020-12-14 00:24:38	136	FADEC_R_CONTINUOUS_RATING_THERMALLY_LIMITED	1	L-ACS	0	0	0
2020-12-14 00:24:40	136	FADEC_R_CONTINUOUS_RATING_THERMALLY_LIMITED	1	R-ACS	0	0	0
2020-12-14 00:24:40	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	1	R-ACS	0	0	0
2020-12-14 00:24:40	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	1	L-ACS	0	0	0
2020-12-14 00:24:40	136	FADEC_R_CONTINUOUS_RATING_THERMALLY_LIMITED	0	R-ACS	0	0	0
2020-12-14 00:24:40	138	FADEC_R_TAKE_OFF_RATING_THERMALLY_LIMITED	1	R-ACS	0	0	0
2020-12-14 00:24:40	136	FADEC_R_CONTINUOUS_RATING_THERMALLY_LIMITED	0	L-ACS	0	0	0
2020-12-14 00:24:40	138	FADEC_R_TAKE_OFF_RATING_THERMALLY_LIMITED	1	L-ACS	0	0	0
2020-12-14 00:24:40	733	PITCH_TRIM_IN_MOTION	0	L-ACS	0	0	0
2020-12-14 00:24:41	733	PITCH_TRIM_IN_MOTION	0	R-ACS	0	0	0
2020-12-14 00:24:41	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:24:41							
2020-12-14 00:24:42	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	0	R-ACS	0	0	0
2020-12-14 00:24:45	137	FADEC_L_TAKE_OFF_RATING_THERMALLY_LIMITED	1	R-ACS	0	0	0
2020-12-14 00:24:45	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	0	L-ACS	0	0	0
2020-12-14 00:24:45	137	FADEC_L_TAKE_OFF_RATING_THERMALLY_LIMITED	1	L-ACS	0	0	0
2020-12-14 00:24:45	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	1	R-ACS	0	0	0
2020-12-14 00:24:45	137	FADEC_L_TAKE_OFF_RATING_THERMALLY_LIMITED	0	R-ACS	0	0	0
2020-12-14 00:24:45	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	1	L-ACS	0	0	0
2020-12-14 00:24:45	137	FADEC_L_TAKE_OFF_RATING_THERMALLY_LIMITED	0	L-ACS	0	0	0
2020-12-14 00:24:45	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:24:49	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:24:50	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:24:52	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:24:52	136	FADEC_R_CONTINUOUS_RATING_THERMALLY_LIMITED	1	R-ACS	0	0	0
2020-12-14 00:24:57	138	FADEC_R_TAKE_OFF_RATING_THERMALLY_LIMITED	0	R-ACS	0	0	0
2020-12-14 00:24:57	136	FADEC_R_CONTINUOUS_RATING_THERMALLY_LIMITED	1	L-ACS	0	0	0
2020-12-14 00:24:57	138	FADEC_R_TAKE_OFF_RATING_THERMALLY_LIMITED	0	L-ACS	0	0	0
2020-12-14 00:24:57	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	0	L-ACS	0	0	0
2020-12-14 00:24:58	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	0	R-ACS	0	0	0
2020-12-14 00:24:58	136	FADEC_R_CONTINUOUS_RATING_THERMALLY_LIMITED	0	R-ACS	0	0	0
2020-12-14 00:24:58	136	FADEC_R_CONTINUOUS_RATING_THERMALLY_LIMITED	0	L-ACS	0	0	0
2020-12-14 00:24:58	136	FADEC_R_CONTINUOUS_RATING_THERMALLY_LIMITED	1	R-ACS	0	0	0
2020-12-14 00:24:58	136	FADEC_R_CONTINUOUS_RATING_THERMALLY_LIMITED	1	L-ACS	0	0	0
2020-12-14 00:24:58	1858	LANDING_LIGHT_SW_ON	0	R-ACS	0	0	0
	1858	LANDING_LIGHT_SW_ON	0	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:25:07							
2020-12-14 00:25:08	1859	STROBE_LIGHT_SW_ON	1	R-ACS	0	0	0
2020-12-14 00:25:08	1859	STROBE_LIGHT_SW_ON	1	L-ACS	0	0	0
2020-12-14 00:25:08	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	1	L-ACS	0	0	0
2020-12-14 00:25:12	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	1	R-ACS	0	0	0
2020-12-14 00:25:12	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	0	R-ACS	0	0	0
2020-12-14 00:25:17	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	0	L-ACS	0	0	0
2020-12-14 00:25:17	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:25:19	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:25:20	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:25:22	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:25:22	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	1	L-ACS	0	0	0
2020-12-14 00:25:29	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	1	R-ACS	0	0	0
2020-12-14 00:25:29	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	0	R-ACS	0	0	0
2020-12-14 00:25:49	135	FADEC_L_CONTINUOUS_RATING_THERMALLY_LIMITED	0	L-ACS	0	0	0
2020-12-14 00:25:49	8226	Ecb:Aft Evap Fan - Low	1	ECBU	0	0	4
2020-12-14 00:27:19	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:27:54	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:27:54	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:27:57	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:27:57	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:28:07	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:28:07	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 00:28:08	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:28:08							
2020-12-14 00:28:13	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 00:28:13	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 00:28:13	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:28:16	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 00:28:18	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
2020-12-14 00:28:18	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:28:19	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:28:19	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 00:28:20	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 00:28:20	8217	Ecb:LH Gen ON	1	ECBU	0	0	4
2020-12-14 00:28:44	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:31:03	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:31:04	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
2020-12-14 00:31:04	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:31:06	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:31:06	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 00:31:06	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 00:31:06	136	FADEC_R_CONTINUOUS_RATING_THERMALLY_LIMITED	0	R-ACS	0	0	0
2020-12-14 00:31:08	136	FADEC_R_CONTINUOUS_RATING_THERMALLY_LIMITED	0	L-ACS	0	0	0
2020-12-14 00:31:09	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:31:14	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:31:14	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 00:31:14	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:31:14							
2020-12-14 00:31:16	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:31:16	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 00:31:16	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 00:31:16	700	L_WINDSHIELD_HEAT_OFF	0	R-ACS	0	0	0
2020-12-14 00:33:51	702	* L_WINDSHIELD_HEAT_ON	1	R-ACS	0	0	0
2020-12-14 00:33:51	700	L_WINDSHIELD_HEAT_OFF	0	L-ACS	0	0	0
2020-12-14 00:33:52	702	* L_WINDSHIELD_HEAT_ON	1	L-ACS	0	0	0
2020-12-14 00:33:52	701	R_WINDSHIELD_HEAT_OFF	0	L-ACS	0	0	0
2020-12-14 00:33:52	703	* R_WINDSHIELD_HEAT_ON	1	L-ACS	0	0	0
2020-12-14 00:33:52	701	R_WINDSHIELD_HEAT_OFF	0	R-ACS	0	0	0
2020-12-14 00:33:52	703	* R_WINDSHIELD_HEAT_ON	1	R-ACS	0	0	0
2020-12-14 00:33:52	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:34:37	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:34:37	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 00:34:38	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
2020-12-14 00:34:39	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:34:40	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:34:40	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 00:34:40	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 00:35:14	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:35:49	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:35:50	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 00:35:50	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:35:50							
2020-12-14 00:35:52	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:35:52	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 00:35:53	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 00:35:53	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:36:04	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:36:04	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 00:36:04	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
2020-12-14 00:36:04	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:36:09	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:36:09	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 00:36:10	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 00:36:10	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:36:18	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:36:18	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 00:36:18	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
2020-12-14 00:36:18	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:36:22	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:36:22	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 00:36:22	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 00:36:22	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:36:25	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:36:25	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 00:36:26	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:36:26							
2020-12-14 00:36:28	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:36:28	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 00:36:29	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 00:36:29	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:36:31	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:36:31	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:36:31	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:36:31	1861	INSPECTION_LIGHT_SW_ON	1	L-ACS	0	0	0
2020-12-14 00:37:09	1861	INSPECTION_LIGHT_SW_ON	1	R-ACS	0	0	0
2020-12-14 00:37:09	1859	STROBE_LIGHT_SW_ON	0	L-ACS	0	0	0
2020-12-14 00:37:11	1860	BEACON_LIGHT_SW_ON	0	L-ACS	0	0	0
2020-12-14 00:37:11	1859	STROBE_LIGHT_SW_ON	0	R-ACS	0	0	0
2020-12-14 00:37:11	1860	BEACON_LIGHT_SW_ON	0	R-ACS	0	0	0
2020-12-14 00:37:11	1861	INSPECTION_LIGHT_SW_ON	0	L-ACS	0	0	0
2020-12-14 00:37:16	1861	INSPECTION_LIGHT_SW_ON	0	R-ACS	0	0	0
2020-12-14 00:37:16	1859	STROBE_LIGHT_SW_ON	1	L-ACS	0	0	0
2020-12-14 00:38:39	1860	BEACON_LIGHT_SW_ON	1	L-ACS	0	0	0
2020-12-14 00:38:39	1859	STROBE_LIGHT_SW_ON	1	R-ACS	0	0	0
2020-12-14 00:38:39	1860	BEACON_LIGHT_SW_ON	1	R-ACS	0	0	0
2020-12-14 00:38:39	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:39:14	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:39:14	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 00:39:14	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:39:14							
2020-12-14 00:39:17	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:39:17	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 00:39:17	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 00:39:17	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:45:37	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:45:37	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 00:45:37	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
2020-12-14 00:45:37	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:45:39	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:45:39	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 00:45:40	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 00:45:40	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:46:03	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:46:03	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:46:09	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:46:09	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:48:28	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:48:28	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:48:30	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:48:30	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:48:51	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:48:51	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:48:54	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:48:54							
2020-12-14 00:53:10	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:53:10	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:53:14	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:53:14	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:56:12	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:56:12	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:56:15	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:56:15	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:56:59	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:56:59	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 00:56:59	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
2020-12-14 00:56:59	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:57:03	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:57:03	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 00:57:04	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 00:57:04	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 00:57:07	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 00:57:07	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 00:57:08	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 00:57:08	1797	PS3_PROBE_L_COMM_FAIL	1	R-ACS	1	1	0
2020-12-14 00:58:24	1797	PS3_PROBE_L_COMM_FAIL	1	L-ACS	1	1	0
2020-12-14 00:58:24	1797	PS3_PROBE_L_COMM_FAIL	0	R-ACS	1	1	0
2020-12-14 00:58:25	1797	PS3_PROBE_L_COMM_FAIL	0	L-ACS	1	1	0
	2042	R_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 00:58:25							
2020-12-14 01:06:50	2042	R_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 01:06:50	2042	R_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 01:06:55	2042	R_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 01:06:55	2042	R_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 01:07:23	2042	R_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 01:07:23	2042	R_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 01:07:43	2042	R_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 01:07:43	2042	R_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 01:07:50	2042	R_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 01:07:50	2042	R_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 01:07:56	2042	R_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 01:07:56	2042	R_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 01:08:43	2042	R_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 01:08:43	2042	R_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 01:08:47	2042	R_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 01:08:47	2042	R_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 01:08:53	2042	R_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 01:08:53	2042	R_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 01:08:56	2042	R_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 01:08:56	2042	R_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 01:09:44	2042	R_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 01:09:44	2042	R_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 01:09:47	2042	R_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
	2042	R_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 01:09:47							
2020-12-14 01:09:55	2042	R_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 01:09:55	2042	R_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 01:10:03	2042	R_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 01:10:03	2042	R_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 01:10:20	2042	R_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 01:10:20	2042	R_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 01:10:29	2042	R_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 01:10:29	2042	R_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 01:10:46	2042	R_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 01:10:47	2042	R_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 01:10:51	2042	R_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 01:10:51	2042	R_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 01:11:00	2042	R_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 01:11:00	2042	R_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 01:11:06	2042	R_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 01:11:06	2042	R_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 01:11:14	2042	R_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 01:11:14	2042	R_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 01:11:15	2042	R_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 01:11:15	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 01:22:41	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 01:22:41	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 01:22:42	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 01:22:42							
2020-12-14 01:22:44	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 01:22:44	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 01:22:44	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 01:22:44	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 01:22:52	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 01:22:52	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 01:22:56	1861	INSPECTION_LIGHT_SW_ON	1	L-ACS	0	0	0
2020-12-14 01:48:35	1861	INSPECTION_LIGHT_SW_ON	1	R-ACS	0	0	0
2020-12-14 01:48:35	1861	INSPECTION_LIGHT_SW_ON	0	L-ACS	0	0	0
2020-12-14 01:48:37	1861	INSPECTION_LIGHT_SW_ON	0	R-ACS	0	0	0
2020-12-14 01:48:37	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 01:49:45	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 01:49:45	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 01:49:49	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 01:49:49	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 01:50:01	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 01:50:01	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 01:50:02	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
2020-12-14 01:50:02	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 01:50:06	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 01:50:06	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 01:50:07	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 01:50:07	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 02:00:18							
2020-12-14 02:00:18	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 02:00:19	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
2020-12-14 02:00:19	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:00:20	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:00:20	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 02:00:21	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 02:00:21	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:00:27	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:00:27	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 02:00:28	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
2020-12-14 02:00:28	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:00:31	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:00:31	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 02:00:32	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 02:00:32	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:02:35	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:02:35	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 02:02:36	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
2020-12-14 02:02:36	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:02:36	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:02:37	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 02:02:39	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 02:02:39	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 02:02:40							
2020-12-14 02:02:40	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 02:02:42	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
2020-12-14 02:02:42	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:02:43	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:02:43	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 02:02:43	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 02:02:44	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:02:48	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:02:48	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 02:02:48	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
2020-12-14 02:02:49	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:02:49	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:02:49	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 02:02:50	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 02:02:50	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:04:46	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:04:47	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 02:04:47	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
2020-12-14 02:04:47	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:04:49	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:04:49	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 02:04:50	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 02:04:50	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 02:04:59							
2020-12-14 02:05:00	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:05:06	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:05:06	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:05:15	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:05:15	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 02:05:16	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
2020-12-14 02:05:16	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 02:05:17	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 02:05:17	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:05:18	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:05:18	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:08:09	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:08:09	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 02:08:12	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
2020-12-14 02:08:12	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 02:08:13	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 02:08:13	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:08:15	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:08:15	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:08:21	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:08:21	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:08:22	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:08:22	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 02:08:29							
2020-12-14 02:08:29	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 02:08:30	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
2020-12-14 02:08:30	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:08:34	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:08:34	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 02:08:35	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 02:08:35	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:08:40	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:08:40	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:08:40	1506	PITCH_DEFAULT_MODE_TRANSITION	1	R-ACS	0	0	0
2020-12-14 02:09:33	1506	PITCH_DEFAULT_MODE_TRANSITION	1	L-ACS	0	0	0
2020-12-14 02:09:33	1506	PITCH_DEFAULT_MODE_TRANSITION	0	R-ACS	0	0	0
2020-12-14 02:09:44	1506	PITCH_DEFAULT_MODE_TRANSITION	0	L-ACS	0	0	0
2020-12-14 02:09:44	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:09:46	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:09:46	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0
2020-12-14 02:09:48	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
2020-12-14 02:09:48	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:09:49	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:09:49	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 02:09:50	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 02:09:50	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:11:37	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
	1976	* L_MMDR_REDUCED_XMIT_PWR	1	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 02:11:37							
2020-12-14 02:11:38	1976	* L_MMDR_REDUCED_XMIT_PWR	1	R-ACS	0	0	0
2020-12-14 02:11:40	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:11:40	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:11:40	1976	* L_MMDR_REDUCED_XMIT_PWR	0	L-ACS	0	0	0
2020-12-14 02:11:40	1976	* L_MMDR_REDUCED_XMIT_PWR	0	R-ACS	0	0	0
2020-12-14 02:11:40	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:11:51	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:11:51	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:11:53	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:11:53	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:11:59	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:11:59	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:12:02	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:13:26	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:13:54	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:13:54	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:13:56	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:13:56	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:14:38	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:14:38	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:14:40	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:14:40	978	ACS_AI_BIT_CONVO_3_WRAP_FAIL	1	R-ACS	1	1	0
2020-12-14 02:17:21	1078	ACS_DO_L_GCU_RESET_FAIL	1	R-ACS	0	0	0
	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 02:17:22							
2020-12-14 02:17:36	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:17:38	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:17:40	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:17:40	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:17:50	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:17:50	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:17:56	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:17:56	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:18:24	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:18:25	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:18:29	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:18:29	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:20:20	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:20:20	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:20:25	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:20:25	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:20:33	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:20:33	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:20:35	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:20:35	1977	* L_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:22:44	1977	* L_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:22:44	1977	* L_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:22:46	1977	* L_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
	2042	R_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 02:22:46							
2020-12-14 02:24:36	2042	R_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:24:36	2042	R_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:24:43	2042	R_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:24:43	2042	R_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:24:54	2042	R_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:24:55	2042	R_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:24:55	2042	R_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:24:55	2042	R_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:25:02	2042	R_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:25:02	2042	R_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:25:02	2042	R_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:25:03	2042	R_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:25:07	2042	R_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:25:07	2042	R_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:25:09	978	ACS_AI_BIT_CONVO_3_WRAP_FAIL	0	R-ACS	1	1	0
2020-12-14 02:25:32	1078	ACS_DO_L_GCU_RESET_FAIL	0	R-ACS	0	0	0
2020-12-14 02:25:32	1858	LANDING_LIGHT_SW_ON	1	L-ACS	0	0	0
2020-12-14 02:26:44	1858	LANDING_LIGHT_SW_ON	1	R-ACS	0	0	0
2020-12-14 02:26:44	1857	TAXI_RECOG_LIGHT_SW_ON	1	L-ACS	0	0	0
2020-12-14 02:26:45	1857	TAXI_RECOG_LIGHT_SW_ON	1	R-ACS	0	0	0
2020-12-14 02:28:16	1569	ROLL_PREFLIGHT_BIT_FAILURE	0	L-ACS	0	0	0
2020-12-14 02:30:18	606	* IN_AIR	0	L-ACS	0	0	0
2020-12-14 02:30:21	606	* IN_AIR	0	R-ACS	0	0	0
	1075	ACS_DO_IN_AIR_FAIL	1	R-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 02:30:21							
2020-12-14 02:30:21	1075	ACS_DO_IN_AIR_FAIL	1	L-ACS	0	0	0
2020-12-14 02:30:45	1584	ROLL_AP_EXCEEDANCE_FAIL	1	R-ACS	0	0	0
2020-12-14 02:30:45	1586	ROLL_AP_DISCONNECT	1	R-ACS	0	0	0
2020-12-14 02:30:45	1584	ROLL_AP_EXCEEDANCE_FAIL	1	L-ACS	0	0	0
2020-12-14 02:30:45	1586	ROLL_AP_DISCONNECT	1	L-ACS	0	0	0
2020-12-14 02:30:45	1480	PITCH_AP_EXCEEDANCE_FAIL	1	R-ACS	1	1	0
2020-12-14 02:30:45	1482	PITCH_AP_DISCONNECT	1	R-ACS	0	0	0
2020-12-14 02:30:45	1876	PITCH_NORMACCELERATION_ENV	1	R-ACS	0	0	0
2020-12-14 02:30:45	1886	PITCH_ISS_ACCEL_ERROR	1	R-ACS	0	0	0
2020-12-14 02:30:45	1480	PITCH_AP_EXCEEDANCE_FAIL	1	L-ACS	0	0	0
2020-12-14 02:30:45	1482	PITCH_AP_DISCONNECT	1	L-ACS	0	0	0
2020-12-14 02:30:45	1876	PITCH_NORMACCELERATION_ENV	1	L-ACS	0	0	0
2020-12-14 02:30:45	1886	PITCH_ISS_ACCEL_ERROR	1	L-ACS	0	0	0
2020-12-14 02:30:45	1532	YAW_AP_EXCEEDANCE_FAIL	1	R-ACS	0	0	0
2020-12-14 02:30:45	1534	YAW_YD_DISCONNECT	1	R-ACS	0	0	0
2020-12-14 02:30:45	1532	YAW_AP_EXCEEDANCE_FAIL	1	L-ACS	0	0	0
2020-12-14 02:30:45	1534	YAW_YD_DISCONNECT	1	L-ACS	0	0	0
2020-12-14 02:30:45	658	DLG_SYS_MISMATCH_NOSE	1	R-ACS	1	1	0
2020-12-14 02:30:46	732	GEAR_UP_WARNING	1	R-ACS	0	0	0
2020-12-14 02:30:46	658	DLG_SYS_MISMATCH_NOSE	1	L-ACS	1	1	0
2020-12-14 02:30:46	732	GEAR_UP_WARNING	1	L-ACS	0	0	0
2020-12-14 02:30:46	748	TAKEOFF_CONFIG_PITCH_TRIM_ERR	1	R-ACS	0	0	0
2020-12-14 02:30:46	8296	TAKEOFF_CONFIG_FLAPS_ERR	1	R-ACS	0	0	0
	658	DLG_SYS_MISMATCH_NOSE	0	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 02:30:46							
2020-12-14 02:30:46	732	GEAR_UP_WARNING	0	L-ACS	0	0	0
2020-12-14 02:30:46	748	TAKEOFF_CONFIG_PITCH_TRIM_ERR	1	L-ACS	0	0	0
2020-12-14 02:30:46	8296	TAKEOFF_CONFIG_FLAPS_ERR	1	L-ACS	0	0	0
2020-12-14 02:30:46	658	DLG_SYS_MISMATCH_NOSE	0	R-ACS	0	0	0
2020-12-14 02:30:46	732	GEAR_UP_WARNING	0	R-ACS	0	0	0
2020-12-14 02:30:46	1480	PITCH_AP_EXCEEDANCE_FAIL	0	R-ACS	1	1	0
2020-12-14 02:30:46	1482	PITCH_AP_DISCONNECT	0	R-ACS	0	0	0
2020-12-14 02:30:46	1532	YAW_AP_EXCEEDANCE_FAIL	0	R-ACS	0	0	0
2020-12-14 02:30:46	1534	YAW_YD_DISCONNECT	0	R-ACS	0	0	0
2020-12-14 02:30:46	1876	PITCH_NORMACCELERATION_ENV	0	R-ACS	0	0	0
2020-12-14 02:30:46	1886	PITCH_ISS_ACCEL_ERROR	0	R-ACS	0	0	0
2020-12-14 02:30:46	1584	ROLL_AP_EXCEEDANCE_FAIL	0	L-ACS	1	1	0
2020-12-14 02:30:47	1586	ROLL_AP_DISCONNECT	0	L-ACS	0	0	0
2020-12-14 02:30:47	1584	ROLL_AP_EXCEEDANCE_FAIL	0	R-ACS	0	0	0
2020-12-14 02:30:47	1586	ROLL_AP_DISCONNECT	0	R-ACS	0	0	0
2020-12-14 02:30:47	1480	PITCH_AP_EXCEEDANCE_FAIL	0	L-ACS	0	0	0
2020-12-14 02:30:47	1482	PITCH_AP_DISCONNECT	0	L-ACS	0	0	0
2020-12-14 02:30:47	1876	PITCH_NORMACCELERATION_ENV	0	L-ACS	1	1	0
2020-12-14 02:30:47	1886	PITCH_ISS_ACCEL_ERROR	0	L-ACS	0	0	0
2020-12-14 02:30:47	1482	PITCH_AP_DISCONNECT	1	L-ACS	0	0	0
2020-12-14 02:30:47	1532	YAW_AP_EXCEEDANCE_FAIL	0	L-ACS	0	0	0
2020-12-14 02:30:47	1877	PITCH_NORMACCELERATION_MISCOMP	1	L-ACS	0	0	0
2020-12-14 02:30:47	1886	PITCH_ISS_ACCEL_ERROR	1	L-ACS	0	0	0
	1586	ROLL_AP_DISCONNECT	1	R-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 02:30:47							
2020-12-14 02:30:47	540	FUEL_AUTO_LAT_CG_TRANSFER_DISABLE	1	L-ACS	0	0	0
2020-12-14 02:30:47	1475	STICK_PUSHER_FAIL	1	L-ACS	1	1	0
2020-12-14 02:30:48	540	FUEL_AUTO_LAT_CG_TRANSFER_DISABLE	1	R-ACS	0	0	0
2020-12-14 02:30:48	1480	PITCH_AP_EXCEEDANCE_FAIL	1	R-ACS	1	1	0
2020-12-14 02:30:48	1482	PITCH_AP_DISCONNECT	1	R-ACS	0	0	0
2020-12-14 02:30:48	1532	YAW_AP_EXCEEDANCE_FAIL	1	R-ACS	0	0	0
2020-12-14 02:30:48	1534	YAW_YD_DISCONNECT	1	R-ACS	0	0	0
2020-12-14 02:30:48	1876	PITCH_NORMACCELERATION_ENV	1	R-ACS	0	0	0
2020-12-14 02:30:48	1886	PITCH_ISS_ACCEL_ERROR	1	R-ACS	0	0	0
2020-12-14 02:30:48	1584	ROLL_AP_EXCEEDANCE_FAIL	1	L-ACS	1	1	0
2020-12-14 02:30:48	1586	ROLL_AP_DISCONNECT	1	L-ACS	0	0	0
2020-12-14 02:30:48	1584	ROLL_AP_EXCEEDANCE_FAIL	1	R-ACS	1	1	0
2020-12-14 02:30:48	1480	PITCH_AP_EXCEEDANCE_FAIL	1	L-ACS	1	1	0
2020-12-14 02:30:48	1876	PITCH_NORMACCELERATION_ENV	1	L-ACS	0	0	0
2020-12-14 02:30:48	1532	YAW_AP_EXCEEDANCE_FAIL	1	L-ACS	1	1	0
2020-12-14 02:30:48	1877	PITCH_NORMACCELERATION_MISCOMP	1	R-ACS	1	1	0
2020-12-14 02:30:49	658	DLG_SYS_MISMATCH_NOSE	1	L-ACS	1	1	0
2020-12-14 02:30:49	732	GEAR_UP_WARNING	1	L-ACS	0	0	0
2020-12-14 02:30:49	658	DLG_SYS_MISMATCH_NOSE	1	R-ACS	1	1	0
2020-12-14 02:30:49	732	GEAR_UP_WARNING	1	R-ACS	0	0	0
2020-12-14 02:30:49	1475	STICK_PUSHER_FAIL	1	R-ACS	1	1	0
2020-12-14 02:30:49	80	R_ENG_OIL_PRESS_LOW_CAUTION	1	R-ACS	0	0	0
2020-12-14 02:30:49	80	R_ENG_OIL_PRESS_LOW_CAUTION	0	R-ACS	0	0	0
	80	R_ENG_OIL_PRESS_LOW_CAUTION	1	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 02:30:50							
2020-12-14 02:30:50	80	R_ENG_OIL_PRESS_LOW_CAUTION	0	L-ACS	0	0	0
2020-12-14 02:30:50	659	DLG_SYS_MISMATCH_LEFT	1	R-ACS	1	1	0
2020-12-14 02:30:50	659	DLG_SYS_MISMATCH_LEFT	1	L-ACS	1	1	0
2020-12-14 02:30:50	1782	FLAPS_FAIL	1	R-ACS	1	1	0
2020-12-14 02:30:50	476	FLAP_OBL_FLAPS_FAIL	1	L-ACS	1	1	0
2020-12-14 02:30:50	479	FLAP_OBR_FLAPS_FAIL	1	L-ACS	0	0	0
2020-12-14 02:30:50	1782	FLAPS_FAIL	1	L-ACS	0	0	0
2020-12-14 02:30:50	1885	PITCH_LATACCELERATION_MISCOMP	1	L-ACS	0	0	0
2020-12-14 02:30:50	476	FLAP_OBL_FLAPS_FAIL	1	R-ACS	0	0	0
2020-12-14 02:30:50	479	FLAP_OBR_FLAPS_FAIL	1	R-ACS	0	0	0
2020-12-14 02:30:50	1798	PS3_PROBE_R_COMM_FAIL	1	R-ACS	1	1	0
2020-12-14 02:30:50	1798	PS3_PROBE_R_COMM_FAIL	1	L-ACS	1	1	0
2020-12-14 02:30:50	1071	ACS_DO_ON_GROUND_2_FAIL	0	L-ACS	0	0	0
2020-12-14 02:30:51	660	DLG_SYS_MISMATCH_RIGHT	1	L-ACS	1	1	0
2020-12-14 02:30:51	1850	TAKEOFF_CONFIG_ENG_TEMP_ERR	1	L-ACS	1	1	0
2020-12-14 02:30:51	660	DLG_SYS_MISMATCH_RIGHT	1	R-ACS	0	0	0
2020-12-14 02:30:51	1850	TAKEOFF_CONFIG_ENG_TEMP_ERR	1	R-ACS	0	0	0
2020-12-14 02:30:51	521	FLAP_IBL_RS485_TIMEOUT	1	L-ACS	0	0	0
2020-12-14 02:30:51	610	GEAR_NOSE_STATUS_NO_COMM	1	L-ACS	0	0	0
2020-12-14 02:30:51	521	FLAP_IBL_RS485_TIMEOUT	1	R-ACS	0	0	0
2020-12-14 02:30:51	1071	ACS_DO_ON_GROUND_2_FAIL	0	R-ACS	0	0	0
2020-12-14 02:30:51	1552	YAW_YAWRATE_ENV	1	L-ACS	0	0	0
2020-12-14 02:30:51	1562	YAW_ISS_RATE_ERROR	1	L-ACS	0	0	0
	1877	PITCH_NORMACCELERATION_MISCOMP	0	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 02:30:51							
2020-12-14 02:30:51	1885	PITCH_LATACCELERATION_MISCOMP	0	L-ACS	0	0	0
2020-12-14 02:30:51	1877	PITCH_NORMACCELERATION_MISCOMP	0	R-ACS	1	1	0
2020-12-14 02:30:51	1552	YAW_YAWRATE_ENV	1	R-ACS	0	0	0
2020-12-14 02:30:51	1562	YAW_ISS_RATE_ERROR	1	R-ACS	0	0	0
2020-12-14 02:30:51	521	FLAP_IBL_RS485_TIMEOUT	0	L-ACS	0	0	0
2020-12-14 02:30:51	610	GEAR_NOSE_STATUS_NO_COMM	0	L-ACS	0	0	0
2020-12-14 02:30:51	521	FLAP_IBL_RS485_TIMEOUT	0	R-ACS	0	0	0
2020-12-14 02:30:51	609	GEAR_RIGHT_COMM_NO_RESPONSE_FAIL	1	R-ACS	1	1	0
2020-12-14 02:30:51	79	L_ENG_OIL_PRESS_LOW_CAUTION	1	L-ACS	0	0	0
2020-12-14 02:30:51	79	L_ENG_OIL_PRESS_LOW_CAUTION	0	L-ACS	0	0	0
2020-12-14 02:30:52	609	GEAR_RIGHT_COMM_NO_RESPONSE_FAIL	1	L-ACS	1	1	0
2020-12-14 02:30:52	1063	ACS_AI_R_WS125_FAIL	1	R-ACS	1	1	0
2020-12-14 02:30:52	1064	ACS_AI_R_WS161_FAIL	1	R-ACS	0	0	0
2020-12-14 02:30:52	1065	ACS_AI_R_WS197_FAIL	1	R-ACS	0	0	0
2020-12-14 02:30:52	1066	ACS_AI_R_WS70_FAIL	1	R-ACS	1	1	0
2020-12-14 02:30:52	1475	STICK_PUSHER_FAIL	0	L-ACS	0	0	0
2020-12-14 02:30:52	1560	YAW_PITCHRATE_ENV	1	L-ACS	0	0	0
2020-12-14 02:30:52	1877	PITCH_NORMACCELERATION_MISCOMP	1	L-ACS	0	0	0
2020-12-14 02:30:52	660	DLG_SYS_MISMATCH_RIGHT	0	L-ACS	0	0	0
2020-12-14 02:30:52	161	EPDS_EPC_TRIP	1	R-ACS	0	0	0
2020-12-14 02:30:52	164	EPDS_SBC_TRIP	1	R-ACS	0	0	0
2020-12-14 02:30:52	181	R_GEN_OFFLINE	1	R-ACS	0	0	0
2020-12-14 02:30:52	660	DLG_SYS_MISMATCH_RIGHT	0	R-ACS	0	0	0
	155	EPDS_SINGLE_GEN_LOAD_SHED	1	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 02:30:52							
2020-12-14 02:30:52	161	EPDS_EPC_TRIP	1	L-ACS	0	0	0
2020-12-14 02:30:52	164	EPDS_SBC_TRIP	1	L-ACS	0	0	0
2020-12-14 02:30:52	181	R_GEN_OFFLINE	1	L-ACS	0	0	0
2020-12-14 02:30:52	4	CPCS_ELECTRICAL_FAIL	1	R-ACS	0	0	0
2020-12-14 02:30:52	155	EPDS_SINGLE_GEN_LOAD_SHED	1	R-ACS	0	0	0
2020-12-14 02:30:52	4	CPCS_ELECTRICAL_FAIL	1	L-ACS	0	0	0
2020-12-14 02:30:52	1065	ACS_AI_R_WS197_FAIL	1	L-ACS	1	1	0
2020-12-14 02:30:52	161	EPDS_EPC_TRIP	0	L-ACS	0	0	0
2020-12-14 02:30:52	164	EPDS_SBC_TRIP	0	L-ACS	0	0	0
2020-12-14 02:30:52	171	EPDS_R_AFT_BUS_FAULT	1	L-ACS	0	0	0
2020-12-14 02:30:52	1064	ACS_AI_R_WS161_FAIL	1	L-ACS	0	0	0
2020-12-14 02:30:52	161	EPDS_EPC_TRIP	0	R-ACS	0	0	0
2020-12-14 02:30:52	164	EPDS_SBC_TRIP	0	R-ACS	0	0	0
2020-12-14 02:30:52	171	EPDS_R_AFT_BUS_FAULT	1	R-ACS	0	0	0
2020-12-14 02:30:52	707	R_WINDSHIELD_HEAT_CURRENT_LOSS_FAIL	1	R-ACS	0	0	0
2020-12-14 02:30:52	1063	ACS_AI_R_WS125_FAIL	1	L-ACS	0	0	0
2020-12-14 02:30:52	1066	ACS_AI_R_WS70_FAIL	1	L-ACS	0	0	0
2020-12-14 02:30:52	1973	* L_PFD_R_ADC_FAIL	1	R-ACS	0	0	0
2020-12-14 02:30:52	2038	R_PFD_R_ADC_FAIL	1	R-ACS	0	0	0
2020-12-14 02:30:52	1973	* L_PFD_R_ADC_FAIL	1	L-ACS	0	0	0
2020-12-14 02:30:52	2038	R_PFD_R_ADC_FAIL	1	L-ACS	0	0	0
2020-12-14 02:30:52	1050	ACS_AI_R_ENGINE_OIL_PRESSURE_FAIL	1	R-ACS	0	0	0
2020-12-14 02:30:52	88	FADEC_R_FADEC_MINOR_INDICATION	1	L-ACS	0	0	0
	74	R_ENGINE_OIL_PRESSURE_FAILED	1	R-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 02:30:52							
2020-12-14 02:30:52	87	FADEC_L_FADEC_MINOR_INDICATION	1	R-ACS	0	0	0
2020-12-14 02:30:52	88	FADEC_R_FADEC_MINOR_INDICATION	1	R-ACS	0	0	0
2020-12-14 02:30:52	169	EPDS_R_FWD_BUS_FAULT	1	L-ACS	0	0	0
2020-12-14 02:30:52	169	EPDS_R_FWD_BUS_FAULT	1	R-ACS	1	1	0
2020-12-14 02:30:52	1379	ONSIDE_STALL_SYSTEM_FAILURE	1	R-ACS	1	1	0
2020-12-14 02:30:52	1380	OFFSIDE_STALL_SYSTEM_FAILURE	1	R-ACS	0	0	0
2020-12-14 02:30:52	1751	R_CSP_BUS_DATA_FAIL	1	R-ACS	0	0	0
2020-12-14 02:30:52	127	FADEC_L_SECONDARY_BUS_LOW_VOLTAGE_FAULT	1	L-ACS	0	0	0
2020-12-14 02:30:53	660	DLG_SYS_MISMATCH_RIGHT	1	L-ACS	0	0	0
2020-12-14 02:30:53	1379	ONSIDE_STALL_SYSTEM_FAILURE	1	L-ACS	0	0	0
2020-12-14 02:30:53	1380	OFFSIDE_STALL_SYSTEM_FAILURE	1	L-ACS	0	0	0
2020-12-14 02:30:53	127	FADEC_L_SECONDARY_BUS_LOW_VOLTAGE_FAULT	1	R-ACS	0	0	0
2020-12-14 02:30:53	660	DLG_SYS_MISMATCH_RIGHT	1	R-ACS	1	1	0
2020-12-14 02:30:53	1051	ACS_AI_R_ENGINE_OIL_TEMP_FAIL	1	R-ACS	0	0	0
2020-12-14 02:30:53	1052	ACS_AI_R_ENG_CHIP_DETECT_FAIL	1	R-ACS	0	0	0
2020-12-14 02:30:53	68	R_ENGINE_CHIP_DETECTOR_FAILED	1	R-ACS	1	1	0
2020-12-14 02:30:53	154	R_OIL_TEMP_SENSOR_FAIL	1	R-ACS	0	0	0
2020-12-14 02:30:53	79	L_ENG_OIL_PRESS_LOW_CAUTION	1	L-ACS	0	0	0
2020-12-14 02:30:53	183	ELECT_ECBU2_NO_COMM	1	R-ACS	0	0	0
2020-12-14 02:30:53	2027	R_CSP_COMM_FAIL	1	L-ACS	0	0	0
2020-12-14 02:30:53	2027	R_CSP_COMM_FAIL	1	R-ACS	0	0	0
2020-12-14 02:30:53	79	L_ENG_OIL_PRESS_LOW_CAUTION	0	L-ACS	0	0	0
2020-12-14 02:30:53	183	ELECT_ECBU2_NO_COMM	1	L-ACS	0	0	0
	707	R_WINDSHIELD_HEAT_CURRENT_LOSS_FAIL	1	L-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 02:30:53							
2020-12-14 02:30:53	79	L_ENG_OIL_PRESS_LOW_CAUTION	1	R-ACS	0	0	0
2020-12-14 02:30:53	1798	PS3_PROBE_R_COMM_FAIL	0	R-ACS	1	1	0
2020-12-14 02:30:53	1050	ACS_AI_R_ENGINE_OIL_PRESSURE_FAIL	1	L-ACS	0	0	0
2020-12-14 02:30:53	1798	PS3_PROBE_R_COMM_FAIL	0	L-ACS	0	0	0
2020-12-14 02:30:53	88	FADEC_R_FADEC_MINOR_INDICATION	0	L-ACS	0	0	0
2020-12-14 02:30:53	1751	R_CSP_BUS_DATA_FAIL	1	L-ACS	1	1	0
2020-12-14 02:30:53	88	FADEC_R_FADEC_MINOR_INDICATION	0	R-ACS	0	0	0
2020-12-14 02:30:53	92	FADEC_R_FADEC_FAIL_INDICATION	1	R-ACS	0	0	0
2020-12-14 02:30:53	74	R_ENGINE_OIL_PRESSURE_FAILED	1	L-ACS	0	0	0
2020-12-14 02:30:53	92	FADEC_R_FADEC_FAIL_INDICATION	1	L-ACS	0	0	0
2020-12-14 02:30:53	79	L_ENG_OIL_PRESS_LOW_CAUTION	0	R-ACS	0	0	0
2020-12-14 02:30:53	1008	ACS_AI_BIT_POWER_SUPPLY_2_MONITOR_FAIL	1	R-ACS	0	0	0
2020-12-14 02:30:53	1008	ACS_AI_BIT_POWER_SUPPLY_2_MONITOR_FAIL	1	L-ACS	0	0	0
2020-12-14 02:30:53	128	FADEC_R_SECONDARY_BUS_LOW_VOLTAGE_FAULT	1	L-ACS	0	0	0
2020-12-14 02:30:53	128	FADEC_R_SECONDARY_BUS_LOW_VOLTAGE_FAULT	1	R-ACS	0	0	0
2020-12-14 02:30:53	1051	ACS_AI_R_ENGINE_OIL_TEMP_FAIL	1	L-ACS	1	1	0
2020-12-14 02:30:53	1052	ACS_AI_R_ENG_CHIP_DETECT_FAIL	1	L-ACS	0	0	0
2020-12-14 02:30:53	68	R_ENGINE_CHIP_DETECTOR_FAILED	1	L-ACS	1	1	0
2020-12-14 02:30:53	154	R_OIL_TEMP_SENSOR_FAIL	1	L-ACS	0	0	0
2020-12-14 02:30:54	676	DEICE_WING_BOOT_SWITCH_DEGRADED	1	R-ACS	1	1	0
2020-12-14 02:30:54	1747	ROLL_SERVO_TROQUE_HIGH	1	R-ACS	1	1	0
2020-12-14 02:30:54	1747	ROLL_SERVO_TROQUE_HIGH	1	L-ACS	0	0	0
2020-12-14 02:30:54	467	R_ENG_FIRE_DETECTOR_FAIL	1	R-ACS	1	1	0
	676	DEICE_WING_BOOT_SWITCH_DEGRADED	1	L-ACS	1	1	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 02:30:54							
2020-12-14 02:30:54	1745	L_AP_SERVO_BUS_DATA_FAIL	1	R-ACS	1	1	0
2020-12-14 02:30:55	1746	R_AP_SERVO_BUS_DATA_FAIL	1	L-ACS	1	1	0
2020-12-14 02:30:55	467	R_ENG_FIRE_DETECTOR_FAIL	1	L-ACS	1	1	0
2020-12-14 02:30:55	8325	LB_STATIC_LOSS_OF_HEAT	1	R-ACS	0	0	0
2020-12-14 02:30:56	691	RA_STATIC_LOSS_OF_HEAT	1	R-ACS	0	0	0
2020-12-14 02:30:56	8325	LB_STATIC_LOSS_OF_HEAT	1	L-ACS	0	0	0
2020-12-14 02:30:56	691	RA_STATIC_LOSS_OF_HEAT	1	L-ACS	0	0	0
2020-12-14 02:30:56	2046	R_TRANSPONDER_COMM_FAIL	1	R-ACS	0	0	0
2020-12-14 02:30:56	2085	SUBSYSTEM_3C_EVENT_BIT_24	1	R-ACS	0	0	0
2020-12-14 02:30:56	2046	R_TRANSPONDER_COMM_FAIL	1	L-ACS	0	0	0
2020-12-14 02:30:56	2085	SUBSYSTEM_3C_EVENT_BIT_24	1	L-ACS	0	0	0
2020-12-14 02:30:56	595	FUEL_WSTIP_FAIL_RIGHT	1	R-ACS	1	1	0
2020-12-14 02:30:57	565	FUEL_GAUGING_FAIL_RIGHT	1	R-ACS	1	1	0
2020-12-14 02:30:57	8276	FUEL_WS161_FAIL_RIGHT	1	R-ACS	0	0	0
2020-12-14 02:30:57	587	FUEL_WS197_FAIL_RIGHT	1	R-ACS	0	0	0
2020-12-14 02:30:57	583	FUEL_WS125_FAIL_RIGHT	1	R-ACS	0	0	0
2020-12-14 02:30:57	591	FUEL_WS70_FAIL_RIGHT	1	R-ACS	0	0	0
2020-12-14 02:30:57	595	FUEL_WSTIP_FAIL_RIGHT	1	L-ACS	1	1	0
2020-12-14 02:30:57	565	FUEL_GAUGING_FAIL_RIGHT	0	R-ACS	0	0	0
2020-12-14 02:30:57	565	FUEL_GAUGING_FAIL_RIGHT	1	L-ACS	1	1	0
2020-12-14 02:30:57	599	FUEL_FILTER_IMP_BYPASS_RIGHT	1	R-ACS	1	1	0
2020-12-14 02:30:57	599	FUEL_FILTER_IMP_BYPASS_RIGHT	1	L-ACS	1	1	0
2020-12-14 02:30:57	587	FUEL_WS197_FAIL_RIGHT	1	L-ACS	1	1	0
	583	FUEL_WS125_FAIL_RIGHT	1	L-ACS	1	1	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 02:30:57							
2020-12-14 02:30:57	8276	FUEL_WS161_FAIL_RIGHT	1	L-ACS	0	0	0
2020-12-14 02:30:57	591	FUEL_WS70_FAIL_RIGHT	1	L-ACS	0	0	0
2020-12-14 02:30:57	565	FUEL_GAUGING_FAIL_RIGHT	1	R-ACS	1	1	0
2020-12-14 02:30:57	12	UNCOMMANDED_STANDBY_MODE_ENTERED	1	L-ACS	1	1	0
2020-12-14 02:30:58	12	UNCOMMANDED_STANDBY_MODE_ENTERED	1	R-ACS	1	1	0
2020-12-14 02:30:58	1850	TAKEOFF_CONFIG_ENG_TEMP_ERR	0	L-ACS	1	1	0
2020-12-14 02:31:00	1850	TAKEOFF_CONFIG_ENG_TEMP_ERR	0	R-ACS	1	1	0
2020-12-14 02:31:00	748	TAKEOFF_CONFIG_PITCH_TRIM_ERR	0	L-ACS	0	0	0
2020-12-14 02:31:00	8296	TAKEOFF_CONFIG_FLAPS_ERR	0	L-ACS	0	0	0
2020-12-14 02:31:00	748	TAKEOFF_CONFIG_PITCH_TRIM_ERR	0	R-ACS	0	0	0
2020-12-14 02:31:00	8296	TAKEOFF_CONFIG_FLAPS_ERR	0	R-ACS	0	0	0
2020-12-14 02:31:00	543	FUEL_CG_WARNING_DISABLE	1	L-ACS	1	1	0
2020-12-14 02:31:02	543	FUEL_CG_WARNING_DISABLE	1	R-ACS	1	1	0
2020-12-14 02:31:02	1076	ACS_DO_L_ENGINE_STOP_FAIL	0	L-ACS	0	0	0
2020-12-14 02:31:12	155	EPDS_SINGLE_GEN_LOAD_SHED	0	L-ACS	0	0	0
2020-12-14 02:31:12	1373	LEFT_BLEED_AIR_AVAIL	0	R-ACS	0	0	0
2020-12-14 02:31:12	1373	LEFT_BLEED_AIR_AVAIL	0	L-ACS	0	0	0
2020-12-14 02:31:12	1076	ACS_DO_L_ENGINE_STOP_FAIL	0	R-ACS	0	0	0
2020-12-14 02:31:12	1077	ACS_DO_R_ENGINE_STOP_FAIL	0	R-ACS	0	0	0
2020-12-14 02:31:13	965	ACS_AI_BIT_CONDO_OG1_WRAP_FAIL	1	L-ACS	1	1	0
2020-12-14 02:31:13	92	FADEC_R_FADEC_FAIL_INDICATION	0	L-ACS	1	1	0
2020-12-14 02:31:13	8325	LB_STATIC_LOSS_OF_HEAT	0	L-ACS	0	0	0
2020-12-14 02:31:13	691	RA_STATIC_LOSS_OF_HEAT	0	L-ACS	0	0	0
	88	FADEC_R_FADEC_MINOR_INDICATION	1	R-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 02:31:13							
2020-12-14 02:31:13	92	FADEC_R_FADEC_FAIL_INDICATION	0	R-ACS	0	0	0
2020-12-14 02:31:13	181	R_GEN_OFFLINE	0	R-ACS	0	0	0
2020-12-14 02:31:13	8325	LB_STATIC_LOSS_OF_HEAT	0	R-ACS	0	0	0
2020-12-14 02:31:13	691	RA_STATIC_LOSS_OF_HEAT	0	R-ACS	0	0	0
2020-12-14 02:31:13	88	FADEC_R_FADEC_MINOR_INDICATION	1	L-ACS	0	0	0
2020-12-14 02:31:13	181	R_GEN_OFFLINE	0	L-ACS	0	0	0
2020-12-14 02:31:13	707	R_WINDSHIELD_HEAT_CURRENT_LOSS_FAIL	0	L-ACS	1	1	0
2020-12-14 02:31:13	1076	ACS_DO_L_ENGINE_STOP_FAIL	1	L-ACS	0	0	0
2020-12-14 02:31:13	1077	ACS_DO_R_ENGINE_STOP_FAIL	0	L-ACS	0	0	0
2020-12-14 02:31:13	1374	RIGHT_BLEED_AIR_AVAIL	0	R-ACS	0	0	0
2020-12-14 02:31:13	543	FUEL_CG_WARNING_DISABLE	0	L-ACS	0	0	0
2020-12-14 02:31:13	543	FUEL_CG_WARNING_DISABLE	0	R-ACS	0	0	0
2020-12-14 02:31:13	1374	RIGHT_BLEED_AIR_AVAIL	0	L-ACS	0	0	0
2020-12-14 02:31:13	707	R_WINDSHIELD_HEAT_CURRENT_LOSS_FAIL	0	R-ACS	1	1	0
2020-12-14 02:31:14	965	ACS_AI_BIT_CONDO_OG1_WRAP_FAIL	1	R-ACS	1	1	0
2020-12-14 02:31:15	1076	ACS_DO_L_ENGINE_STOP_FAIL	1	R-ACS	0	0	0
2020-12-14 02:31:15	19	RIGHT_FCVA_FAIL	1	L-ACS	1	1	0
2020-12-14 02:31:15	31	CCS_RIGHT_FCV_FAIL	1	L-ACS	0	0	0
2020-12-14 02:31:15	19	RIGHT_FCVA_FAIL	1	R-ACS	1	1	0
2020-12-14 02:31:15	31	CCS_RIGHT_FCV_FAIL	1	R-ACS	0	0	0
2020-12-14 02:31:15	8216	Ecb:Radar Altimeter	1	ECBU	0	0	2
2020-12-14 02:31:17	8217	Ecb:LH Gen ON	1	ECBU	0	0	2
2020-12-14 02:31:19	8217	Ecb:LH Gen ON	0	ECBU	0	0	2
	8217	Ecb:LH Gen ON	0	ECBU	0	0	4

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 02:31:23							
2020-12-14 02:31:23	19	RIGHT_FCVA_FAIL	0	L-ACS	1	1	0
2020-12-14 02:31:23	31	CCS_RIGHT_FCV_FAIL	0	L-ACS	0	0	0
2020-12-14 02:31:23	19	RIGHT_FCVA_FAIL	0	R-ACS	1	1	0
2020-12-14 02:31:23	31	CCS_RIGHT_FCV_FAIL	0	R-ACS	0	0	0
2020-12-14 02:31:23	567	FUEL_LOW_FUEL_LEVEL_RIGHT	1	L-ACS	1	1	0
2020-12-14 02:31:26	567	FUEL_LOW_FUEL_LEVEL_RIGHT	1	R-ACS	1	1	0
2020-12-14 02:31:27	554	FUEL_LAT_CG_WARNING	1	R-ACS	0	0	0
2020-12-14 02:31:27	177	EPDS_SYS_BATT_DISCHARGING	1	R-ACS	0	0	0
2020-12-14 02:31:27	177	EPDS_SYS_BATT_DISCHARGING	1	L-ACS	0	0	0
2020-12-14 02:31:27	554	FUEL_LAT_CG_WARNING	1	L-ACS	0	0	0
2020-12-14 02:31:28	8223	Ecb:L Ignition	0	ECBU	0	0	4
2020-12-14 02:31:28	599	FUEL_FILTER_IMP_BYPASS_RIGHT	0	R-ACS	1	1	0
2020-12-14 02:31:36	599	FUEL_FILTER_IMP_BYPASS_RIGHT	0	L-ACS	1	1	0
2020-12-14 02:31:36	730	MASTER_CAUTION_DISABLE	1	L-ACS	1	1	0
2020-12-14 02:31:39	730	MASTER_CAUTION_DISABLE	1	R-ACS	1	1	0
2020-12-14 02:31:41	569	FUEL_R_SUMP_LOW	1	R-ACS	1	1	0
2020-12-14 02:31:41	571	FUEL_FWSOV_FAIL_RIGHT	1	R-ACS	1	1	0
2020-12-14 02:31:42	571	FUEL_FWSOV_FAIL_RIGHT	1	L-ACS	1	1	0
2020-12-14 02:31:42	8226	Ecb:Aft Evap Fan - Low	0	ECBU	0	0	4
2020-12-14 02:32:00	8227	Ecb:L Anti-Collision Lt	0	ECBU	0	0	4
2020-12-14 02:32:02	2042	R_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:32:11	2042	R_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:32:11	8237	Ecb:L Main Landing Gear	0	ECBU	0	0	4
	2042	R_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0

Event Log							
Date	Event ID	Event	Asserted	Channel	SatCom	Engine	Status
2020-12-14 02:32:11							
2020-12-14 02:32:14	2042	R_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:32:14	2042	R_MMDR_XMITTER_ACTIVE	1	R-ACS	0	0	0
2020-12-14 02:32:32	2042	R_MMDR_XMITTER_ACTIVE	1	L-ACS	0	0	0
2020-12-14 02:32:32	2042	R_MMDR_XMITTER_ACTIVE	0	R-ACS	0	0	0
2020-12-14 02:32:35	2042	R_MMDR_XMITTER_ACTIVE	0	L-ACS	0	0	0
2020-12-14 02:32:35	1858	LANDING_LIGHT_SW_ON	0	L-ACS	0	0	0
2020-12-14 02:32:38	1857	TAXI_RECOG_LIGHT_SW_ON	0	L-ACS	0	0	0
2020-12-14 02:32:38	1857	TAXI_RECOG_LIGHT_SW_ON	0	R-ACS	0	0	0
2020-12-14 02:32:38	1858	LANDING_LIGHT_SW_ON	0	R-ACS	0	0	0
2020-12-14 02:32:39	1859	STROBE_LIGHT_SW_ON	0	L-ACS	0	0	0
2020-12-14 02:32:39	1859	STROBE_LIGHT_SW_ON	0	R-ACS	0	0	0
2020-12-14 02:32:40	8216	Ecb:Radar Altimeter	0	ECBU	0	0	2
2020-12-14 02:33:44	8216	Ecb:Radar Altimeter	0	ECBU	0	0	4
2020-12-14 02:34:50	1860	BEACON_LIGHT_SW_ON	0	L-ACS	0	0	0
2020-12-14 02:34:50	1860	BEACON_LIGHT_SW_ON	0	R-ACS	0	0	0
2020-12-14 02:36:20	568	FUEL_L_SUMP_LOW	1	R-ACS	1	1	0
2020-12-14 02:36:20	568	FUEL_L_SUMP_LOW	1	L-ACS	1	1	0
2020-12-14 02:37:55	11	RIGHT_FCV_SHUTDOWN	1	R-ACS	0	0	0
2020-12-14 02:38:02	11	RIGHT_FCV_SHUTDOWN	1	L-ACS	0	0	0
2020-12-14 02:38:02	10	LEFT_FCV_SHUTDOWN	1	L-ACS	0	0	0
2020-12-14 02:38:03	10	LEFT_FCV_SHUTDOWN	1	R-ACS	0	0	0
2020-12-14 02:38:03	163	EPDS_BBC_TRIP	1	L-ACS	1	1	0
2020-12-14 02:38:07	163	EPDS_BBC_TRIP	1	R-ACS	1	1	0
	658	DLG_SYS_MISMATCH_NOSE	0	R-ACS	1	1	0

Event Log						
Date	Event ID	Event	Asserted	Channel	SatCom	Engine Status
2020-12-14 02:38:07						