

YEAR 2020		RECORDING TACH. READING	TIME THIS FLIGHT	TOTAL TIME	REMARKS	SIGNATURE
11	1	331.00		694.33		
20	20	Performed 160 hr insp. Cleaned & gap plugs. Performed Compression Check #1 79/80 #2 69/80 #3 72/80 #4 72/80 #5 68/80 #6 71/80 no oil change at this time.				
		[REDACTED]				

CARRY TOTAL TIME TO TOP OF NEXT PAGE

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2020 11-1-20	331.0		4051.33	Aircraft inspected IAW an Annual inspection. Replaced ECT battery PIN BP-1010 Dec Sept 2022, replaced Air filter with BA7112 replacement element. Performed gear retraction test and emergency gear retraction. [REDACTED]

DATE _____

19