



RECORD OF CONVERSATION

John Brannen
Senior Air Safety Investigator
Central Region

Date: September 8, 2021
Person Contacted: Tom Brown – Curtis Municipal Airport Manager
NTSB Accident Number: CEN21LA206

Narrative:

During a telephone conversation, Mr. Brown confirmed that he is the manager of the Curtis Municipal Airport in Curtis, Nebraska. I asked him if he was aware of the accident involving N2955D, and he indicated that he was aware. I asked about the fuel tank at the airport and he provided the following information.

- The airport has above ground tank.
- It is double wall and over 30 years old.
- Somehow it got water between the inner and outer tank which rusted out the inner tank and got water in the fuel.
- The airport has ordered a new tank and currently doesn't sell fuel until the new tank is installed.

I asked if the tank had sediment and water separating filters installed and he indicated that the old fuel tank did not have filters installed but that he has ordered them with the new tank, and will include a water separating filter.