



RECORD OF CORRESPONDENCE

Mitchell Gallo
Aviation Accident Investigator
Central Region

Person Contacted: Bob Benja, RLB Accessory Service, Addison, Illinois
Date: November 29, 2021
NTSB Accident Number: CEN21LA208

During a telephone conversation, Bob Benja stated that the magnetos passed bench testing. The carburetor was disassembled and there were no mechanical anomalies that would have precluded normal operation.

Mitchell Gallo