

San Angelo, Texas 76906

Hobbs; 531.7 N274CV

New Empty weight; 1045.2

New C. G.;	77.81
------------	-------

New Moment; 81,329.32

Useful Load; 754.8

Frank E. Hinds

ADDITIONS AND REMOVALS
S, SERIAL NUMBERS.

Precision Aircraft Services

San Angelo, Texas 76906

Date: 09-03-2020

Hobbs; 564.1 N274CV

Removed all inspection panels and inspect aircraft. Inspect and lubed all wheel bearings. AD 17-16-01 Ameri-King ELT removed for replacement, new ELT on order. Changed oil filter (CH48110-1 filter). Cut open old filter and found no metal contamination. C/W VANS SB 16-03-28 by inspecting inboard aileron hinge and found no cracks. Tightened left exhaust brace upper mount bolt. Tightened loose wiring on lower fuel pressure sending unit. Retorqued Senenich prop per 3FOM. Rotated left tire for wear. Cleaned and reinstalled wiring on oil temperature probe. C/W VANS SB 14-02-05 By inspecting Elevator attach rod end nut plates for cracks, no cracks found. C/W SB 14-01-31 Horizontal Stabilizer checked for cracks and found none.

I certify that this aircraft has been inspected in accordance with an on condition inspection and was determined to be in airworthy condition.

Frank E. Hinds

Precision Aircraft Services

San Angelo, Texas 76906

Date: 09-22-2020

Hobbs; 564.1 N274CV

Removed and replaced Ameri-King ELT with Kannad Amerifit Retrofit AF Integra ELT per DOC11014 installation manual. No weight and balance change.

Frank E. Hinds

15 chg. ID
checksum.

Precision Aircraft Services

San Angelo, Texas 76906

Date: 12-28-2020

Hobbs; 583.9

N274CV

Installed new oil temperature probe. Repaired ACS A-510-2 ignition switch wiring by installing jumper on pin 1. Run up ops checked good.

Frank E. Hinds

MOVALS
(S.

Poor Boy Avionics of San Angelo 8734 Hangar Road San Angelo, TX 76904 CRS0Y0R041J
LOG ID# 929 24-May-2021 WO# 4932
N274CV S/N 81039 VANS RV8 TACH 590.0

Pg 1/2

**** ITEM # 4932-1 G3 install ****

DISCREPANCY: G3 install

ACTION: Removed the Instruments and panel from the aircraft to facilitate the new panel configuration for the G3 install.

Installed the new panel, Experimental G3 system, GTX375 ADSB transponder, and GTR200 in accordance with the Garmin installation instructions.

Equipment:

G3X (GDU 460) s/n 753759119270

GTR 200 s/n 5JC001602

GTX 375 s/n 5GJ004261

GAE 24 s/n 2J2020297

GMU 11 s/n 56J024040

Log book entry was made and weight and balance was made by weighing the aircraft empty fuel. Fuel that was removed was restored to the aircraft using filter funnel for calibration of the G3 system.

The aircraft was ground run by the owner to confirm all systems operational.

**** ITEM # 4932-2 Oil change ****

Poor Boy Avionics of San Angelo 8734 Hangar Road San Angelo, TX 76904 CRS0Y0R041J
LOG ID# 929 24-May-2021 WO# 4932
N274CV S/N 81039 VANS RV8 TACH 590.0

Pg 2 / 2

DISCREPANCY: Oil Change
Oil changed by owner with assistance.

**** ITEM # 4932-3 Fuel leak ****

DISCREPANCY: Fuel leak

ACTION: NJB 4-20-21 Removed and Replaced both Right and Left Fuel Tank Sender Gasket and Tank Gasket
System was checked for leaks on 5/24/21 during calibrations check of the G3 system. No leaks were
noted at this time.

Total time not recorded last log entry 583.9 hrs

Signed RM

Thomas Dufresne

Date

5/24/21

TACH
TIME

TOTALS THIS PAGE

AMT. FORWARD

TO-DATE TOTAL