



RECORD OF CONVERSATION

Aaron M. Sauer
Aviation Accident Investigator
Central Region

Date: 08/17/2021
Person Contacted: Southern Aircraft Recovery Mr. TW Cook
RE: CEN21LA357

Narrative:

During a telephone conversation, Mr. TW Cook stated during the recovery of the airplane, the chemical hopper had contained a puncture hole that leaked into one of the fuel tanks. During the recovery process of draining the fuel tanks, the fuel tanks contained about 7 to 8 gallons of a fuel/chemical mixture. There was no evidence of about 160 gallons of fuel at the accident site or in the airplane fuel tanks.