



Photo 1 – View of airplane showing engine sagging (FAA photo)




Photo 2 – View of bent engine mount (FAA photo)