



MEMORANDUM FOR RECORD

John M. Brannen II
Senior Air Safety Investigator
Central Region

Date: 10/26/2022
NTSB Accident Number: CEN21LA395

Medical and Pathological Information:

An autopsy of the pilot was performed by the Cuyahoga County Medical Examiner's Office, Cleveland, Ohio. The cause of death was due to blunt impact injuries.