



Photo 1 – Lower Part of Fuselage Buckled (Source: Kent State)



Photo 2 – Wrinkles in Lower Part of Fuselage (Source: Kent State)



Photo 3 – Closeup of Popped Rivets in Lower Part of Fuselage (Source: Kent State)