



INVESTIGATION FINDINGS

Jason Aguilera
Air Safety Investigator
Central Region

During the course of the investigation, FAA Inspector David Schluep responded to the accident scene and collected information. When talking with the pilot, the pilot informed him that the loss of engine power was due to fuel mismanagement.

An NTSB Form 6120 was emailed to the pilot, but not returned.

---END---