



RECORD OF INTERVIEW

Michael J. Folkerts
Aviation Accident Investigator
Central Region

NTSB Accident Number: CEN21LA468

Mr. Brandon Bridges provided the following information concerning the accident:

- Following a 20-minute personal flight with the flight instructor (Mr. Hayes), Mr. Bridges made a landing on Runway 13 from the front seat.
- Mr. Bridges and Mr. Hayes swapped seat positions and Mr. Hayes departed from Runway 13 and flew a tight visual traffic pattern.
- Mr. Bridges stated he wasn't really paying much attention to the flight path of the airplane during the traffic pattern.
- As the airplane turned toward final from a right base position, Mr. Bridges noticed a high sink rate had developed.
- The airplane subsequently impacted short of the runway with right wing first.
- Mr. Bridges did not notice a mechanical issue with the airplane during the flight and the flight instructor did not communicate any issue.