



MEMORANDUM FOR RECORD

Aaron Sauer
Sr. Air Safety Investigator
Central Region

Date: 02/09/22
NTSB Accident Number: CEN22FA017

An autopsy of the pilot was performed by the University of North Dakota School of Medicine and Health Sciences, Grand Forks, North Dakota, which listed the cause of death as blunt force trauma. The manner of death was suicide.