

**Choice Aviation, LLC**

Cody, WY Shop – COD

Cody, WY 82414

Customer Invoice
Work Order: COD2791

11/1/2021

Reg. No: N744Z

2002 Piper Pa-46-500TP

Current A/C TT: 1601.8, A/C Landings:

Hobbs: 1601.8

A/C Serial: 4697134

Created on: 10/8/2021

Clint Devin

Total Balance Due:

\$

(See Below For Cost Detail)

Item: 1 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Stall warning test inop. Stall warning works fine	2.00	

Corrective Action

Troubleshoot stall warning system. Found LC does not send signal to warning horn in ground configuration.

Pin all wires from LC to the transducer. Check ok.

Safe Flight recommends changing transducer.

Labor: \$	Parts: \$0.00	Shipping: \$0.00	Outside Repair: \$0.00	Item Subtotal: \$
-----------	---------------	------------------	------------------------	-------------------

Item: 2 - Airworthy Airframe

Discrepancy	Hours	Subtotal
Per owner, Oil pressure is high for about 30 seconds right when I start the airplane and then goes down without issue	N/C	0.00

Corrective Action

During cold engine start oil psi rose to 140psi. This is within limits of 200psi max. for cold weather start IAW

Piper PA46 Pilots Operating Handbook, Section 2 Limitations, pg. 2-3 & 2-4.

Labor: \$0.00	Parts: \$0.00	Shipping: \$0.00	Outside Repair: \$0.00	Item Subtotal: \$0.00
---------------	---------------	------------------	------------------------	-----------------------

Please see the next page for the totals for this invoice

Additional Charges							
Pilot Services	Tire Disposal	Call Out	Oil Analysis	Shop Supplies	Fuel	Misc.	Subtotal
0.00	0.00	0.00	0.00	[REDACTED]	0.00	0.00	\$ [REDACTED]

Labor Summary	
Shop Labor: \$ [REDACTED]	Outside Repair: \$0.00

2.37 hours were needed to complete this Work Order

Taxed Items:

Call Out, Misc. Charges, Shop Parts, Shipping In, Shop Supplies

Tax Breakdown: (Before Calculated)

Call Out: 0.00

Misc. Charges: 0.00

Shop Parts: 0.00

Shipping In: 0.00

Shop Supplies: [REDACTED]

Total Labor: \$ [REDACTED]

Total Parts: \$0.00

Total Shipping: \$0.00

Total Outside Repair: \$0.00

Additional Charges: \$ [REDACTED]

Tax: \$ [REDACTED]

Amount Due: \$ [REDACTED]

Deposit: \$0.00

Balance Due: [REDACTED]

Important Information

Clint Devin or Authorized Representative

Date

John Duffy

General Manager / Director of Maintenance

Mountain Aircraft Maintenance Inc.

Shop

Mobile

Fax

gmail.com

Steamboat Springs, CO 80487

Mountain Aircraft Maintenance, Inc

Steamboat Springs, CO 80477

December 6, 2021 Hobbs 1636.3

N744Z Piper PA46-500TP S/N 4697134

Cleaned and adjusted vacuum regulator. Ground ran engine and operational check of vacuum system ops check good in accordance with PA-46-500TP AMM 37-00-00. John Duffy A&P

[Signature]
[Redacted]