



MEMORANDUM FOR RECORD

Aaron Sauer
Sr. Air Safety Investigator
Central Region

Date: 10/24/22
NTSB Accident Number: CEN22FA070

An autopsy of the pilot was performed by the Office of the Chief Medical Examiner, Tulsa, Oklahoma, which listed the cause of death as multiple blunt force injuries.