

Carburetor Icing Probability Graph – CEN22FA208

Airplane: Piper PA32-260

Engine: Lycoming O-540-E4B5

Accident Date: 05/22/2022

Accident Location: Broomfield, CO

Accident Time: 1149 MDT

Weather: METAR KEIK 221755Z AUTO 19008KT 10SM
BKN046 BKN075 12/M01 A3020

Celsius to Fahrenheit Conversion:

Temperature, 12° C = 53.6° F

Dew Point, -1° C = 30.2° F

Source: Federal Aviation Administration

Special Airworthiness Information Bulletin CE-09-35
Carburetor Icing Prevention

