

From: [REDACTED]
To: [REDACTED]
Subject: Correspondence with FAA
Date: Monday, March 14, 2022 9:03:46 PM

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Mike,

The only anomaly noted in the fuel system was that when the fuel valve was turned on, fuel continuously ran directly through the carburetor and out of the bottom of the engine.

All fuel controls were connected and appeared to work correctly.

I also included a link to a video of the fuel coming out of the carburetor when the fuel valve was opened and surveillance footage of the crash below.

[REDACTED]
[REDACTED]

Let me know if there is anything else you need.

J. Patras

Federal Aviation Administration

Aviation Safety Inspector, Houston Flight Standards District Office
12650 N Featherwood Drive Suite 230, Houston, TX 77034