

Total Air Group

Work Order:		Title:	Sky Bound Aviation LLC	Status:	Closed
Registration #:		Department:	MS-MX	P.O. #:	
Customer:	Sky Bound Aviation LLC	Contact Name:		Created:	
Address:		Account Code:		Posted:	
		Target Date:		Job #:	
		Invoice #:			
		Date Closed:	12/27/2021		

Item:	1	Model #:		Serial #:	B-179
Squawk:	1	Discrepancy:	TS AUTOFEATHER SYSTEM		
		Resolution:	TROUBLESHOT AUTOFEATHER SYSTEM ON GROUND/ON JACKS AND WITH GEAR EXTENDED AND RETRACTED. FOUND LOW PRESSURE SWITCH ON L/H ENG TO BE INOP. R/R LOW PRESSURE SWITCH IAW KING AIR A100 MM 61-21-00. OPS CHECK GOOD. PERFORMED MULTIPLE GROUND RUNS AND SYSTEM TESTS WITH NO DEFECTS NOTED. A/C OK FOR SERVICE.		
		Completed:	12/27/2021	By:	Michelle Heffron (MHEFFRON)
		*** End of Document ***			