

RECORD OF ☐ VISIT ☐ CONFERENCE OR ☒ TELEPHONE CALL		TIME 4:51 PM	DATE 01/11/2022
NAME (S) OF PERSON (S) CONTACTED OR IN CONFERENCE AND LOCATION Thomas Heimes (pilot) - [REDACTED]		ROUTING 	
		SYMBOL	INITIALS
ROC - Steve			
SUBJECT N1333C runway departure during attempted go-around			
DIGEST Received a call from the Regional Operations Center about a Cessna 177B that departed the runway during an attempted go-around. Mr. Heimes (certificate # [REDACTED]) stated that he took off from MLE to practice some landings at AHQ (Wahoo), then continue back to MLE. During landing at Wahoo, the airplane floated, the left wing lifted, the pilot over-corrected and initiated a go-around but as he powered up, failed to apply sufficient right rudder to counter the engine torque and departed the runway. According to the pilot, damage to the airplane includes the left wing, prop, and landing gear. There were two people on board, with no injuries. Approximate time of the incident was 1600. Mr. Heimes said he would take pictures of the damage and email them to me.			
CONCLUSION, ACTION TAKEN, OR REQUIRED Will investigate to determine extend of damage.			
DATE 01/11/2022	TITLE Bud Carlson - FLM	SIGNATURE [REDACTED] Digitally signed by RUSSELL L CARLSON Date: 2022.01.12 06:34:08 -06'00'	