



Timothy Sorensen
Sr. Aviation Accident Investigator
Aviation Safety - Central Region

Date: February 24, 2022
Subject: CEN22LA102 - Grand Forks, North Dakota
Contact: Insp. Kelly Bosch / Insp. Sean Mosher - FAA Flight Standards

Inspectors Bosch and Mosher provided the following information regarding the post-recovery airplane examination:

- The examination was completed after the airplane was recovered to a hangar at the airport.
- The landing gear motor jack screw was in the up (retracted) position.
- Electrical power did not appear to be reaching the gear extension motor.
- Once the nose landing gear doors were opened, the landing gear was able to be extended manually.

----- *end of summary* -----