



RECORD OF CONVERSATION

Timothy N. Sorensen
Aviation Accident Investigator
Central Region

Date: February 17, 2022
Person Contacted: Don Adamson
NTSB Accident Number: CEN22LA121 – Furlow, AR

Narrative:

Mr. Adamson recovered the airplane from the accident site. He noted that the right fuel tank was compromised; however, it did contain some fuel. He estimated that 1 or 2 gallons ran out of the right tank when the airplane was leveled for recovery. He stated that the left fuel tank appeared to be intact; however, it did not contain any fuel at that time. He commented that first responders reported a strong fuel smell at the site.

----- *end of entries* -----