



RECORD OF CONVERSATION

Aaron M. Sauer
Senior Air Safety Investigator
Central Region

Date: 02/23/2022
Person Contacted: DEN FAA FSDO Inspector Wolfmeier
RE: CEN22LA130

Narrative:

According to Inspector Wolfmeier, postaccident examination of the airplane revealed no issues with flight control continuity from the cockpit controls to the elevator and rudder. The parking brake was found in the OFF position. No anomalies or failures were noted with the airplane. The cockpit voice recorder was located and coordination with a local maintenance facility for removal was in progress.

A witness, who was another pilot and located on the ASE airport ramp, stated that he was “stunned they started the takeoff roll with the wind conditions.”