



Photo 1 – View of bent wing and wing strut (Photo provided by FAA)



Photo 2 – View of bent engine mount tubes (Photo provided by FAA)