



MEMORANDUM FOR RECORD

Shaun Williams
Senior Aviation Accident Investigator
Central Region

Date: 6/23/2022
NTSB Accident Number: CEN22LA165

Airport Association President Emails

Mr. Dave Elliott, President of the Airport Association sent an email to the NTSB on April 3, 2022 describing the damage to airport property. In the email, he stated that it appeared the aircraft departed the left side of runway 15 just before taxiway A3. The sign was damaged as well as several runway and taxiway lights. Also, 1 of the main landing gears had separated on the opposite side of the taxiway intersection. He said the aircraft traveled through a drainage ditch and impacted a paint hangar on the south side of taxiway F. The wing separated as the aircraft cartwheeled over the hangar and impacted the ground on the south side before tumbling.

End of Record