



10001 American Drive
Amarillo, Texas
79111

Date: 5/13/2022 N619AC SN: 421C0336 Hobbs Reads: 6878.0

EFA WO: APMX3269

Re-rigged elevator trim system adjusted up and down travel stops IAW 421 Service Manual Chapter 5. Indexed indicator to proper position in relation to trim tab. Removed right landing light, manually retracted into housing. Collared landing light circuit breakers and installed INOP placard. Added new tail number placard to pilot panel. Removed LH master cylinder and installed new seals IAW 421 Service manual. Bled LH brake and ops check normal. Installed new LED taxi light p/n 01-0771833-20. Ops check normal.

This aircraft is approved for return to service regarding the work performed.

Gregory Langham

A&P

Signature: _____

English Field Aviation, LLC.