



The National Transportation Safety Board

Office of Aviation Safety
Central Region
Memorandum for the Record
Pilot Report Summary
CEN22LA207
Gainesville, Texas
May 19, 2022

Information provided by the pilot to the NTSB:

- The pilot reported that while on final the airplane was bouncing around in gusty wind conditions. He was focusing on the wing gusts, and he forgot to put the gear down.
- The airplane touched down on its belly and slid to a stop. As the pilot exited the airplane, he observed smoke emitting from the engine and as he walked away, the airplane was consumed by fire.

Alexander Lemishko

Senior Air Safety Investigator
NTSB Central Region Aviation