

DATE	REGISTRATION	ENGINE SN	AIRCRAFT SN
10/20/2021	N5007R	At602	1330.2

I hereby authorize **R.T. Turbines, Inc.** to do the repair work set forth below and authorize such testing procedures as they may deem necessary. An express mechanic's lien is hereby acknowledged. I agree to hold **R.T. Turbines, Inc.** blameless for any losses above the limits of their liability.

X

R.T. TURBINES, INC.

OFFICE:

• MARIANNA, AR 72360

• FAX:

CRS # MW9R610J

Form RTT1 01

WORK ORDER

No. 3554

White
Pink
Yellow
Goldenrod

- W.O. Orig.
- Inv. Copy
- Accounting
- Num.Sec.

MATERIAL USED

[illegible]

NAME _____

Southern Aircraft Service

ADDRESS

CITY

STATE

ZIP

England

AR

72046

MAKE & MODEL

ENGINE S/N

TOTAL HOURS	
-------------	--

PT6A-60AG

PC E RG0035

11409.6

TERMS:

Countyline

SERVICE DESCRIPTION

Engine split at the "C" flange for inspection. Installed new compressor turbine shroud segments and new seal ring. Trued and balanced CT disk. Installed O/H T5 harness. Reassembled and tested engine satisfactorily. Engine split at the "C" flange post-run with no rub. All work performed I/A/W current P&W O/H/M PN: 3034343 rev 45.

MAINTAINENCE RELEASE

The component identified above was repaired in accordance with the applicable regulations of the Federal Aviation Administration and is determined to be in airworthy condition and is approved for return to service.

Date 5/23/22

Signed

For: R.T. Turbines, Inc.

TOTAL LABOR

PARTS

FREIGHT												
---------	--	--	--	--	--	--	--	--	--	--	--	--

REPAIR -

TAX

TOTAL

WORK ORDER # 3554 DATE 5/23/22

[illegible]

Total

ENGINE MDL

ENGINE SN

AIRCRAFT SN