

From: [REDACTED]
To: [REDACTED]
Subject: 452VC
Date: Friday, August 12, 2022 8:44:21 AM

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Hi Aaron,
After Oshkosh [REDACTED], we finally got into the engine. What we found was Craig put the push rod on #5 cylinder in upside down when he replaced the exhaust valve. It took about 5 hours before the failure occurred. The rest of the engine appears to be OK. We can send the parts if you still want them. Let me know.
I want to thank you again for all of your help and kindness.
Valerie Westedt