



Timothy Sorensen
Sr. Aviation Accident Investigator
Aviation Safety - Central Region

Date: November 17, 2022
Subject: CEN22LA330 - Wardsville, Missouri
Contact: Lee Allen - Acme Aviation

Mr. Allen replaced the oil filter adapter on N1228Z in February 2022 due to an oil leak. He described the leak as "just a line of oil." The adapter was not loose at that time. The adapter was reinstalled with new copper gaskets and using a new (calibrated) torque wrench.

----- end of summary -----