

NATIONAL TRANSPORTATION SAFETY BOARD
RELEASE OF WRECKAGE

ACCIDENT/INCIDENT
IDENTIFICATION NUMBER
CEN22LA378

PART I - RELEASE OF WRECKAGE

REGISTERED OWNER (name and address) ACP Enterprises LLC [REDACTED] Millington, TN 38053		REGISTRATION OR IDENTIFICATION NUMBER N9637X
		MAKE Cessna
MODEL 210	DATE OF ACCIDENT/INCIDENT August 09, 2022	LOCATION Clinton, AR
The National Transportation Safety Board has ☐ has not ☒ completed its investigation of the wreckage described above. All wreckage except that listed on the reverse side is hereby released to the registered owner, or owner's representative, for appropriate disposition. (If no parts are retained, insert NONE.)		
<u>HYDRAULIC ACTUATOR P/N EA161492, S/N 190</u>		
SIGNATURE OF NTSB REPRESENTATIVE [REDACTED]	TITLE Senior Aviation Accident Investigator	DATE 09/06/2022

(This section may be signed by a person, not the owner or owner's representative, who has knowledge of the disposition of the wreckage and its parts. Such signature does not place responsibility for disposition of the wreckage upon that person.)

I HEREBY ACKNOWLEDGE:

- ☒ Receipt of the above described wreckage.
- ☐ Removal of the parts, if any, listed on the reverse side of this form.

SIGNATURE [REDACTED]	TITLE President	DATE 9/8/22
REMARKS:		

NATIONAL TRANSPORTATION SAFETY BOARD
RECEIPT OF PARTS

ACCIDENT/INCIDENT
IDENTIFICATION NUMBER
CEN22LA378

PART II - RELEASE OF PARTS

REGISTRATION NUMBER

N9637X

MAKE

Cessna

MODEL

182L

DATE OF ACCIDENT/INCIDENT

December 03, 2021

LOCATION

Clinton, AR

The National Transportation Safety Board has retained, for further examination, those parts, pieces, or components listed below. When the examination is complete, they will be returned to:

OWNER OR OWNER'S REPRESENTATIVE - Dawson Aircraft, Inc

ADDRESS

Clinton, AR 72031

PARTS, PIECES, OR COMPONENTS RETAINED:

Hydraulic Actuator P/N EA161492, S/N 190

SIGNATURE OF NTSB REPRESENTATIVE

TITLE

DATE

Senior Aviation Accident Investigator

09/06/2022

The registered owner or owner's representative will acknowledge receipt of the materials by signing this form in the spaces designated

SIGNATURE OF OWNER OR OWNER'S REPRESENTATIVE

TITLE

DATE

ADDRESS

Pres. et al

9/8/22

**NATIONAL TRANSPORTATION SAFETY BOARD
MATERIALS LABORATORY DIVISION
RECEIPT OF RETURNED PARTS**


ACCIDENT/INCIDENT IDENTIFICATION		
PLACE:	Clinton, AR	
DATE / VEHICLE:	August 9, 2022	Cessna 210B, N9637X
NTSB NO. / IIC:	CEN22LA378	Shaun Williams, AS-CEN
THE FOLLOWING PARTS, PIECES OR COMPONENTS, FROM THE ABOVE ACCIDENT/INCIDENT		
See reverse side for inventory list		9 lbs.
ARE BEING RETURNED VIA (CARRIER NAMED):		UPS
WITH TRACKING NUMBER:		[REDACTED]
WHICH HAS BEEN ADDRESSED TO:		
NAME :		
COMPANY :	Dawson Aircraft, Inc.	
ADDRESS :	[REDACTED] Clinton, AR 72031	
TELEPHONE:	[REDACTED]	

PLEASE VERIFY THAT THE COMPONENTS, AS ITEMIZED, HAVE BEEN RECEIVED BY PRINTING YOUR NAME, SIGNING, AND DATING THIS FORM BELOW, AND RETURNING THIS DOCUMENT TO:

Mike Budinski, CHIEF, MATERIALS LABORATORY DIVISION (RE-30),
NATIONAL TRANSPORTATION SAFETY BOARD
[REDACTED]
WASHINGTON, DC 20594.

A PREADDRESSED, STAMPED ENVELOPE IS ATTACHED FOR YOUR CONVENIENCE.

IF ANY DISCREPANCIES ARE FOUND, IMMEDIATELY CALL [REDACTED]



WRITER'S NAME AND INITIALS	Erik M Mueller	DATE	03/21/2023
NTSB REPRESENTATIVE	Erik M Mueller	DATE	03/21/2023
PACKING PARTS			
NAME AND SIGNATURE OF RECIPIENT OR RECIPIENT'S REPRESENTATIVE	<i>Will Dawson</i> Print Sign	DATE	4/11/23

Inventory List:

- Remainder of Landing Gear Actuator Assembly
- Screws (2)
- Washers (2)
- Housing fracture surface (circumferential)
- Housing fracture surface (longitudinal)
- Retainer plate
- Retaining ring
- Housing sections (2)
- Metallographic mount