

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Baton Rouge State: LA

ZIP: 70807 Country: United States Of America

Latitude: 30.54N Longitude: 91.14W

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 08/18/2022 Local Time: 08:52
mm/dd/yyyy

Time Zone: CST

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N17747

Manufacturer: Beechcraft

Model: F33A

Serial Number: CE-704

Year of Manufacture: 1977

Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

☒ IFR-Equipped and Certified

☐ Commercial Space Flight

☐ Unmanned Aircraft

Maximum Gross Weight: 3500 lbs

Weight at Time of Accident/Incident: 2980 lbs

Number of Seats: 4 Flight Crew Seats: 1

Cabin Crew Seats: _____ Passenger Seats: 3

Number of Engines: _____

Category of Aircraft

- ☒ Airplane
- ☐ Balloon
- ☐ Blimp/Dirigible
- ☐ Glider
- ☐ Gyroplane
- ☐ Helicopter
- ☐ Powered Lift
- ☐ Rocket
- ☐ Ultralight
- ☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☐ Normal
- ☐ Aerobatic
- ☐ Balloon
- ☐ Commuter
- ☐ Transport
- ☒ Utility

Special

- ☐ Restricted
- ☐ Limited
- ☐ Provisional
- ☐ Special Flight
- ☐ Experimental
- ☐ Special Light-Sport
- ☐ Experimental Light-Sport

- ☐ Certificate of Authorization or Waiver (COA)
- ☐ None
- ☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

- ☒ Tricycle
- ☐ Amphibian
- ☐ Emergency Float
- ☐ Float
- ☐ Hull
- ☐ Other Launch/Recovery System
- ☐ None
- ☐ Tailwheel
- ☐ High Skid
- ☐ Skid
- ☐ Ski
- ☐ Ski/Wheel
- ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating
- ☐ Turbo Shaft
- ☐ Turbo Prop
- ☐ Turbo Jet
- ☐ Turbo Fan
- ☐ Electric
- ☐ Liquid Rocket
- ☐ Solid Rocket
- ☐ Hybrid Rocket
- ☐ None
- ☐ Unknown

Fuel System Type (Reciprocating)

- ☐ Carburetor
- ☒ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Continental	IO-520	280940-R	04/15/1994	285	727.1	727.1	727.1
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour
- ☐ AAIP
- ☒ Annual
- ☐ Continuous Airworthiness
- ☐ Conditional Inspection
- ☐ Unknown

Date Last Inspection: 12/14/2021
mm/dd/yyyy

Airframe Total Time: 2132.19 hrs

hours measured at (Select one)

- ☐ Last Inspection
- ☒ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☒ Annual
- ☐ Conditional (Amateur-built only)
- ☐ Manufacturer's Inspection Program
- ☐ Other Approved Inspection Program (AAIP)
- ☐ Continuous Airworthiness
- ☐ Other, specify: _____

Description of Fire Extinguishing System

- ☒ None
- ☐ Specify: _____

Propeller 1

- ☐ Fixed Pitch
- ☒ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: Mccauley

Model: PHC-C3YF-1RF/F8068

Propeller 2

- ☐ Fixed Pitch
- ☐ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: Artex Aircraft Supplies

Model or Part No.: 453-6603

TSO No.: ☒ C91 (121.5 MHz) ☐ C91a (121.5 MHz)
☐ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☒ Yes ☐ No

If activated:

Did ELT Aid in Locating Aircraft? ☐ Yes ☒ No

If not activated:

- Indicate Reason:
- ☐ Impact Damage
 - ☐ Fire Damage
 - ☐ Battery Expired/Damaged
 - ☐ Unknown

Additional Equipment (Check all that apply)

- ☒ ADS-B
- ☐ Airframe Parachute
- ☐ Angle of Attack Indicator
- ☒ Autopilot
- ☐ Data Recorder
- ☒ Electronic Flight Bag or Handheld Device
- ☐ Electronic Multifunction Display
- ☒ Electronic Primary Flight Display
- ☐ Handheld GPS
- ☐ Heads Up Display
- ☐ Onboard Weather
- ☐ Satellite Tracking Device
- ☐ Stall Warning System
- ☐ Video Recording Device
- ☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Davis 180 LLCCity: Baton RougeFractional Ownership Aircraft: ☐ Yes ☒ NoState: LA ZIP: 70809Country: USA**Operator of Aircraft**☐ Same As Registered Owner☐ Same Address as Registered OwnerName: Daniel B DavisCity: Baton Rouge

Doing Business As: _____

State: LA ZIP: 70808

Air Carrier/Operator Designator (4 Character Code): _____

Country: USA**Operating Certificates Held**

(Check all that apply)

- ☐ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☒ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)**Airport Name: Baton Rouge Metropolitan AirportDistance From Airport Center: 6 smAirport Identifier: KBTRDirection From Airport: 040 degrees trueProximity to Airport: ☒ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/AAirport Elevation: 70 ft. msl**Runway Information**Runway ID: 22R (L/R/C) Length: 7500 ft Width: 100 ft**Runway/Landing Surface (Check all that apply)**

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☒ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☐ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☒ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
- ☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☒ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☐ Yes ☒ No

"Flight Crewmember 1" Identification

First Name: Daniel City of Residence: Baton Rouge
 Middle Initial: B State: LA ZIP: _____
 Last Name: Davis Country: United States of America
 Age at time of Accident/Incident: 49 Date of Birth: mm/dd/yyyy
 Certificate Number:

Degree of Injury ☒ None ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious	Seat Occupied ☒ Left ☐ Front ☐ Unknown ☐ Right ☐ Rear ☐ Center ☐ Single	Restraint Type <table style="width: 100%;"> <tr> <th style="text-align: left;">Available</th> <th style="text-align: left;">Used</th> </tr> <tr> <td>☐ None</td> <td>☐ None</td> </tr> <tr> <td>☐ Lap only</td> <td>☐ Lap only</td> </tr> <tr> <td>☒ 3-point</td> <td>☒ 3-point</td> </tr> <tr> <td>☐ 4-point</td> <td>☐ 4-point</td> </tr> <tr> <td>☐ 5-point</td> <td>☐ 5-point</td> </tr> <tr> <td>☐ Unknown</td> <td>☐ Unknown</td> </tr> </table>	Available	Used	☐ None	☐ None	☐ Lap only	☐ Lap only	☒ 3-point	☒ 3-point	☐ 4-point	☐ 4-point	☐ 5-point	☐ 5-point	☐ Unknown	☐ Unknown	Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Available	Used																
☐ None	☐ None																
☐ Lap only	☐ Lap only																
☒ 3-point	☒ 3-point																
☐ 4-point	☐ 4-point																
☐ 5-point	☐ 5-point																
☐ Unknown	☐ Unknown																
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☒ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer		Medical Certificate ☐ None ☒ Class 3 ☐ Class 1 ☐ Driver's License (Sport Pilot only) ☐ Class 2 ☐ Unknown															
Principal Occupation ☐ Pilot ☒ Other ☐ Unknown	Medical Certificate Validity ☒ Without limitations/waivers ☐ Unknown ☐ With limitations/waivers ☐ N/A ☐ Special Issuance		Date of Last Medical <u>07/13/2022</u> mm/dd/yyyy														

Medical Certificate Limitations

N/A

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

10/05/2021
mm/dd/yyyy

Flight Review Aircraft

Make: Cessna

Model: 172N

Airplane Rating(s) (Check all that apply) ☐ None ☒ Single-Engine Land ☐ Single-Engine Sea ☐ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) (Check all that apply) ☐ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	Instrument Rating(s) (Check all that apply) ☐ None ☐ Airplane ☐ Helicopter ☐ Powered Lift	Instructor Rating(s) (Check all that apply) ☐ None ☐ Instrument Airplane ☐ Airplane Single-Engine ☐ Instrument Helicopter ☐ Airplane Multi-Engine ☐ Helicopter ☐ Gyroplane ☐ Glider ☐ Powered Lift ☐ Sport
---	---	---	---

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	142.0	27.7	142		4.2	3.1	8			
Pilot in Command (PIC)	38.5	15.6	59				5			
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

"FLIGHT CREWMEMBER 2" INFORMATION

"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident

☒ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 2" Identification

First Name: Christopher City of Residence: Baton Rouge
 Middle Initial: G State: Louisiana ZIP: 70817
 Last Name: O'Neal Country: United States of America
 Age at time of Accident/Incident: 22 Date of Birth: mm/dd/yyyy
 Certificate Number:

Degree of Injury ☒ None ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious	Seat Occupied ☐ Left ☐ Front ☐ Unknown ☒ Right ☐ Rear ☐ Center ☐ Single	Restraint Type <table style="width: 100%;"> <tr> <th style="text-align: left;">Available</th> <th style="text-align: left;">Used</th> </tr> <tr> <td>☐ None</td> <td>☐ None</td> </tr> <tr> <td>☐ Lap only</td> <td>☐ Lap only</td> </tr> <tr> <td>☒ 3-point</td> <td>☒ 3-point</td> </tr> <tr> <td>☐ 4-point</td> <td>☐ 4-point</td> </tr> <tr> <td>☐ 5-point</td> <td>☐ 5-point</td> </tr> <tr> <td>☐ Unknown</td> <td>☐ Unknown</td> </tr> </table>	Available	Used	☐ None	☐ None	☐ Lap only	☐ Lap only	☒ 3-point	☒ 3-point	☐ 4-point	☐ 4-point	☐ 5-point	☐ 5-point	☐ Unknown	☐ Unknown	Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Available	Used																
☐ None	☐ None																
☐ Lap only	☐ Lap only																
☒ 3-point	☒ 3-point																
☐ 4-point	☐ 4-point																
☐ 5-point	☐ 5-point																
☐ Unknown	☐ Unknown																
Pilot Certificate(s) (Check all that apply) ☐ None ☒ Flight Instructor ☒ Commercial ☐ US Military ☒ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☒ Student ☐ Sport ☐ Flight Engineer		Medical Certificate ☐ None ☐ Class 3 ☒ Class 1 ☐ Driver's License (Sport Pilot only) ☐ Class 2 ☐ Unknown															
Principal Occupation ☒ Pilot ☐ Other ☐ Unknown		Medical Certificate Validity ☒ Without limitations/waivers ☐ Unknown ☐ With limitations/waivers ☐ N/A ☐ Special Issuance															
Date of Last Medical <u>12/14/2022</u> mm/dd/yyyy																	

Medical Certificate Limitations

N/A

Medical Certificate Special Issuance

N/A

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

06/29/2021
 mm/dd/yyyy

Flight Review Aircraft

Make: Cessna

Model: 172S

Airplane Rating(s) (Check all that apply) ☐ None ☒ Single-Engine Land ☐ Single-Engine Sea ☒ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) (Check all that apply) ☐ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	Instrument Rating(s) (Check all that apply) ☐ None ☒ Airplane ☐ Helicopter ☐ Powered Lift	Instructor Rating(s) (Check all that apply) ☐ None ☒ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift ☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport
--	---	--	--

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	1200	50	1120	80	150	125	85			
Pilot in Command (PIC)	1100	50	1070	35	140	125	70			
Time as Instructor	200	50	200							
This Make/Model					5	5				
Last 90 Days	200	25	170	30	40	20				
Last 30 Days	70	15	64	6	11	5				
Last 24 Hours										

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)						
Crew Name and Address				Seat Occupied		Injury
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____				☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign				Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs				
Crew Name and Address				Seat Occupied		Injury
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____				☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign				Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs				
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)						
Name and Address		Seat	Injury	Restraint Type		Inflatable Restraints
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>KBTR</u> City: <u>Baton Rouge</u> State: <u>Louisiana</u> Country: <u>United States of America</u>	Time of Departure Time: <u>08:40</u> Time Zone: <u>CST</u>	Destination Airport ID: <u>KBTR</u> City: <u>Baton Rouge</u> State: <u>Louisiana</u> Country: <u>United States of America</u>	Type Flight Plan Filed ☐ None ☐ Company VFR ☐ Military VFR ☐ VFR ☐ VFR/IFR ☒ IFR ☐ Unknown Activated? ☐ Yes ☐ No ☐ Unknown
---	---	--	---

Type of ATC Clearance/Service (Check all that apply)

☐ None	☐ Special VFR	☐ Special IFR	☐ VFR Flight Following	☐ Cruise
☐ VFR	☒ IFR	☐ VFR On Top	☐ Traffic Advisory	☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A ☐ Class B ☒ Class C ☐ Class D ☐ Class E	☐ Class G ☐ Demo Area ☐ Warning Area ☐ Prohibited Area ☐ Restricted Area	☐ Military Operations Area (MOA) ☐ Airport Advisory Area ☐ Jet Training Area ☐ TRSA ☐ FAR 93	☐ Special ☐ Air Traffic Control Area ☐ Unknown	Altitude of In-Flight Occurrence: <u>700</u> ft msl
---	---	---	---	---

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

☐ National Weather Service ☐ Flight Service Station ☐ TV/Radio ☒ Automated Report ☐ Commercial Weather Service (DUATS) ☐ On-Board Weather	☐ Company ☐ Military ☐ Internet ☐ None ☐ Unknown
---	---

Weather Observation Facility

Facility ID: KBTR
 Observation Time: _____
 Time Zone: CST
 Distance from Accident Site: .4 nm
 Direction from Accident Site: 040 degrees true

Basic Conditions

☒ VMC
☐ IMC
☐ Unknown

Light Condition

☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☒ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

☐ Clear ☐ Thin Broken
☐ Few ☐ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☒ Scattered

Lowest Cloud Condition Height

1200 ft agl

Ceiling

☐ None (Clear) ☐ Obscured
☐ Broken ☐ Indefinite
☒ Overcast ☐ Unknown

Ceiling Height

5000 ft agl

Temperature: 27 (C) or 80.6 (F)

Dew Point: 26 (C) or 78.8 (F)

Altimeter Setting: 29.97 in. Hg
or _____ MB

Wind Direction

☐ Variable

-or-
Direction: 320 degrees true

Wind Speed

☐ Calm
☐ Light and Variable

-or-
Speed: 4 kts

Wind Gusts

☐ Not Gusting

-or-
Speed: _____ kts

Visibility 10 miles

RVR: _____ feet

RVV: _____ miles

Density Altitude: 1462 ft

Intensity of Precipitation

☐ Light
☐ Moderate
☐ Heavy
☒ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

☒ None	☐ Drizzle	☐ Freezing Rain
☐ Rain	☐ Ice Pellets	☐ Snow Shower
☐ Snow	☐ Snow Pellets	☐ Ice Pellets Shower
☐ Hail	☐ Snow Grains	☐ Freezing Drizzle
☐ Rain Showers	☐ Ice Crystals	

Restriction to Visibility (Check all that apply)

☒ None	☐ Fog
☐ Blowing Dust	☐ Ground Fog
☐ Blowing Sand	☐ Haze
☐ Blowing Snow	☐ Ice Fog
☐ Blowing Spray	☐ Smoke
☐ Dust	☐ Unknown

Icing Forecast

Amount	Type
☒ None	☐ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Icing Actual

Amount	Type
☒ None	☐ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Turbulence

Type (Check all that apply)	Severity
☒ None	☐ Light
☐ Clear Air	☐ Moderate
☐ Terrain-Induced	☐ Severe
☐ Convective Turbulence	☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☒ Substantial
☐ Minor ☐ Destroyed
☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Propeller damage to two out of three spokes, Landing gear substantially damaged, Wings, fuel tanks, leading and trailing edge surface damage.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

The incident taking place on August 18, 2022 regarding F33A bonanza N17747 that resulted in an off airport landing was caused by a loss of engine power. The reason for the flight on 8/18/22 was for insurance competency for the owner of the aircraft, Daniel Davis. The plan for the day was to remain in the pattern at KBTR for an 8:30 departure, where the owner of the aircraft Daniel Davis would act as pilot in command, while practicing landings and general handling of the aircraft. After checking the weather and notams for the Baton Rouge airport before departure both myself and Daniel decided that the airport was in good enough condition to safely conduct the flight. Upon arrival Daniel, as pilot in command, completed a pre-flight inspection to completing the necessary items listed in the POH. I then arrived after Daniel completed his preflight inspection, where I asked him about the condition of the aircraft and from there, I completed my own walk around to where I found the aircraft airworthy as well. We then reviewed what we intended to complete on today's flight and boarded the aircraft. From this point Daniel Davis was established as pilot in command where we set out for the traffic pattern. After obtaining ATIS information Uniform, we then determined that the weather was still suitable for our intended flight. Dan was instructed to taxi from the northwest tee hangars to runway 22 right. Before taxiing, Daniel Completed the before takeoff checklist items and all items were within tolerance and were deemed airworthy. Daniel then contacted the tower and we were cleared for the right traffic pattern for runway 22R. We departed the runway, and shortly after takeoff we both realized that the weather was worse than broadcasted, I immediately asked for a local IFR clearance back to the KBTR airport via the ILS 22R. At this point in time I then become pilot in command. We were then cleared back to the airport via present position, radar vectors and to maintain 2,500 ft. We then began our vectors and setting up for the approach and landing. Once we were cleared for the approach and became established on the ILS, I then Placed the flap selector at 15 degrees and brought the gear down. I realized we were high once visual contact was made with the field at around 1,500 ft. I then began to reduce the pitch of the plane down slightly and reduce the power. At around 1,000 ft I started to reduce the power where I felt a small bump and then immediately felt the engine cease to create power and then I confirmed this by looking at our manifold pressure gauge. I started going through the engine restarting procedure, to include establishing our Vg speed of 110 Kt, full power and mixture, checking both magnetos and trying to re crank the engine. Once these procedures were not successful, I then called mayday, declared an emergency and we were re cleared to land any runway. I began to start to look for a suitable place to put the aircraft down once I realized that we would not be able to reach the airport. I saw an opening just shy of plank road that was the best option possible. I then glided into the field clipping the tops of a tree, shortly thereafter impacting a small hill where we bounced over a drainage canal impacted again and slid to a halt shortly after. After the aircraft came to a stop I instructed an evacuation of the aircraft to where myself and Daniel climbed out over the top of the wing and ran away from the aircraft.

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

The accident could have been prevented by the engine continuing to operate as normal. Another Solution that should be taken into account is the approach end of the runway gives little to no options for off airport emergency landings. the areas surround the approach end should be cleared as much as possible for events such as this.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)Was there Mechanical Malfunction/Failure? ☒ Yes ☐ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Continental IO-520 BA, SN: 280940-R,

The engine, after a reduction of power, abruptly ceased to create power at a low altitude, a restart was attempted however, was unsuccessful.

Total Time/Cycles On Part

727.1 Hours

N/A Cycles

Time Since This Part Inspected/Overhauled

727.1 Hours

FUEL & SERVICES INFORMATION**Fuel on Board at Last Takeoff**

(Convert from pounds, as necessary)

34 Gallons

Fuel Type☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive**Other Services, if Any, Prior to Departure****EVACUATION OF AIRCRAFT**Was an emergency evacuation of the aircraft performed? ☒ Yes ☐ No**Method of Exit** – Describe how the occupants exited and how many occupants evacuated each location

Upon coming to a stop, Christopher Gage O'Neal commanded an evacuation of the aircraft. The evacuation was done through the main door of the aircraft on the copilots side. Christopher O'Neal exited the aircraft first and then Daniel Davis exited and met at a safe distance away from the aircraft.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)

Aircraft Registration Number

Manufacturer: _____

Model: _____

Damage to Other Aircraft☐ Destroyed☐ Minor☐ Substantial☐ None**Registered Owner of Other Aircraft**

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

08/24/2022
mm/dd/yyyy

Name of Pilot/Operator: Christopher Gage O'Neal

Signature: _____

-- or -- ☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: Daniel B Davis

Title: Owner

Signature: _____

-- or -- ☒ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.
CEN22LA391

Reviewed by NTSB Regional Office
Central Region

Name of Investigator
Andrew Todd Fox

Date Report Received
29 Aug 2022