

N46202 - G/SNA: 1721 S/N: 17257104 Tach Time: [REDACTED]

Replaced existing rear white position light with uAvionix tailBeacon assembly p/n UAV-1002183. Installed in accordance with tailBeacon STC install guide DOCS UAV-10025-001.

Configuration: Anonymous mode: OFF, Call Sign: N46202, IACO Number: 513215574, Emitter Type: Light.

All work performed in accordance with AC43.13-1B and AC43.13-2A. No change to weight and balance.

Date: 06-09-2021

Paul Bruder A&P [REDACTED] A

6-1-22 TACH 2328.3 TTA 3308.3

- 1 ALL WORK DONE USING COSSNA MANUALS AND OTHERS.
- 2 SERVICED BRAKES.
- 3 CHECKED ADS SEE THE MASTER LIST USING T&ATA.
- 4 CW 91-207 (d) ✓ OK
- 5 NEW BA-6100

AIRCRAFT
I certify this 6-1-22 has been
inspected in accordance with an annual
inspection and was determined to be air worth
Date 6-1-22

Beacon Aviation [REDACTED]
LOG ID# 7 10-July-2022 WOR# 100
N46202 S/N 17257104 CESSNA

ATSOA S/N: 34995 Mode A/C Tr
Appendix F.

Altitude reporting system w

This aircraft airframe, ai
accordance with current re
to service.

Inspector/Authorized Sig

for Beacon Aviation of M

7-10-22 TACH

1 INSTAL

AAP [REDACTED]

ENGINE LOG

is certify this ENGINE has been
inspected in accordance with an annual
inspection and was determined to be air worth
Date 6-1-22