

Taylor Aviation Services - 301 Airport Road, Taylor, Texas 76574
N86GV (Airframe log)
Date: 26 August, 2022
Hobbs Time: 203.1

- Preformed condition inspection IAW FAR 43 appendix D.
- Lubed all flight control rod ends, hinges and bell cranks.
- ELT inspected IAW FAR 91.207. Ops check satisfactory. Replaced batteries. Next replacement due by March, 2023.
- Cowling, interior, and inspection panels reinstalled.
- C/W SB00053. Stop drilled crack FWD of the F-1208 bulkhead. Fabricated and installed patch plate and reinforcement clips.

Justin D. Hromcik
A&P [REDACTED] IA

20

Wartungsübersicht / Maintenance recordDatum:
Date:Betriebsstunden:
Engine hours:Gesamt:
TSN:seit letzter GÜ.:
TSO:Durchgeführte Arbeiten:
Work performed:Unterschrift &
LFZ Wart Nr.:
Signature &
Licence no.:

Taylor Aviation Services - 301 Airport Road, Taylor, Texas 76574
N86GV (Powerplant log)
Date: 26 August, 2022
Hobbs Time: 203.1

-Performed condition inspection.

I certify this aircraft has been inspected in accordance with a condition inspection and is determined to be in airworthy condition.

Justin D. Hromcik
A&P IA