

DATE	PROPELLER TSN TSO	A/C Hrs.	Description of Service
Aug 27 2019	00:00 -	-	Manufactured, TBO 3600 hrs. or 72 months. [REDACTED]

Repair Station RN0R650X/EASA.145.6339
ENGINEERING CORP.
[REDACTED] Spokane, WA 99212 [REDACTED] Fax [REDACTED]

Aircraft: N 963MA Model: PA46-350P Serial #: 4636453 Total Time: 1197.6 Hobbs: 1197.6 Work Order #: REC-2019- 07
Propeller Model #: MTV-16-1-E-C-F-R (P) Propeller Serial #: 190792 Propeller Total Time: 0

THIS PROPELLER WAS INSTALLED IAW THE JETPROP STC ST00541SE IAW THE MANUFACTURE'S INSTRUCTIONS. THE ENGINE/PROPELLER COMBINATION HAS BEEN DYNAMICALLY BALANCED. THIS PROPELLER IS CONSIDERED AIRWORTHY AND IS APPROVED FOR SERVICE.

I certify the aircraft identified above was inspected in accordance with current regulations of the FAA and is approved for return to service.
Details are on file at this repair station under work order REC-2019- 07
Date: 02-11-20 Authorized Signature: Chris G. Hansen Certificate #: [REDACTED]

[REDACTED]

Form Rec-25

Page _____

DATE PROP
TSN



Propeller Entry 03-05-2021

N963MA MTV-16-1-E-C-F-R (P) S/N 4636453 PTSN 115.0 hrs.

Removed Prop for Repair.


Randall Huelsman [REDACTED] AP/IA [REDACTED] 03-05-2021

Page _____

WWW.MT-PROPELLER.COM

DATE PROPELLER A/C

Description of Service

DATE	PROPELLER TSN TSO	A/C Hrs.	Description of Service				
			 INTERCONTINENTAL JET SERVICE CORP 				
			Propeller Model	Component	Serial No.	T.S.O.	T.S.N
			MTV-16-1-N-C-F-R(P)	Propeller	190792	N/A	115.0
			Blade Model	Blade No. 1	AKE-76471		
			CFR206-58a	Blade No. 2	AKE-76742		
			Date	Blade No. 3	AKE-76743		
			4/7/2021	Blade No. 4	AKE-76474		
			Disassembled propeller, cleaned area, replaced leading edge and deice boot on blade #4. Reassembled propeller with new seals and statically balanced in accordance with MT Maintenance Manuals E680 Rev. 46, E808 Rev. 12 and E1290 Rev. 45. Work performed in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Details of repairs are on file with this Repair Station under Work Order 2737.				
			Signed  for INTERCONTINENTAL JET SERVICE CORP FAA Repair Station # IZ2R916K Hangar 27-Tulsa, Oklahoma				



[REDACTED] OLATHE, KS 66062 [REDACTED] [REDACTED]

Propeller log book entry

N963SB HC-E4N-3N S/N HH4866 HM 1686.6 hrs. Total time 552.1 hrs

Inspected propeller per MAS Jetprop inspection guide. Lubricated hub and filed nicks from blades. Performed run-up and functional checks. Operations are satisfactory.

I certify that this propeller has been inspected in accordance with an annual inspection and was found to be in airworthy condition. Kevin Mead [REDACTED] 3-10-2021 IA
[REDACTED]

Page _____

WWW.MT-PROPELLER.COM

DATE	PROPELLER TSN TSO	A/C Hrs.	Description of Service

[illegible]