

Alexander Lemishko
Senior Air Safety Investigator
NTSB, Central Region

Date: May 14, 2023

Subject: Memorandum for the Record CEN23FA187
Owner Interview Summary

Contacts: Alexander Lemishko - NTSB IIC

Maintenance logbooks and pilot logbooks were not available. The NTSB IIC interviewed the airplane owner, and he provided the following information:

He estimated the pilot's flight times:

Total flight time - about 1,300 hours.
Total time in make and model – about 30 hours.
Last 30 Days – about 3 hours.

He estimated the airplane's total time to be about 3,700 hours, and its most recent annual inspection was on about July 15, 2022. He estimated the engine total time to be about 3,700 hours, with its most recent overhaul at about 2,000 hours.

He stated that the flight originated from Newton, Kansas, and was intended to land at Glen Ullin, North Dakota.

Owner - Eugene Pearson [REDACTED]

Alexander Lemishko
[REDACTED]

NTSB Senior Air Safety Investigator
Denver, Colorado