

Michael Hodges

From: Eick Donald
Sent: Thursday, July 13, 2023 15:23
To: Hodges Michael
Cc: Rodi Jennifer
Subject: CEN23FA304 - Osage Beach, MO Weather

Follow Up Flag: Flag for follow up
Flag Status: Flagged

Notification: At 12:15 PM CDT, July 13, 2023, Osage Beach, MO. Piper PA-28-140 (N8225N) crashed shortly after takeoff from Grand Glaize Airport (K15). 3 POB; 2 fatal, 1 serious. M. Hodges (CEN) responding. MR Support: S. Sulick. Srce: J. Rodi (CEN)

1215 CDT (1715Z)

Grand Glaize-Osage Beach Airport (K15), Osage Beach, Missouri, elevation 876 ft, magnetic variation of 0. No weather reporting capability.
Nearest reporting station:

Lee C. Fine Memorial Airport (KAIZ), Kaiser/Lake Ozark, MO, 5nm E, AWOS, elv. 868 ft

METAR KAIZ 131556Z AUTO 27007KT 240V320 10SM BKN017 28/23 RMK AO2 SLPNO T02780233 \$

SPECI KAIZ 131649Z AUTO VRB05KT 10SM SCT025 29/23 RMK AO2 \$

METAR KAIZ 131656Z AUTO VRB06KT 10SM BKN025 30/23 RMK AO2 SLPNO T03000233 \$

Accident 1715Z

SPECI KAIZ 131725Z AUTO VRB05KT 10SM FEW027 31/23 RMK AO2 \$

METAR KAIZ 131756Z AUTO 27005KT 10SM FEW029 31/23 RMK AO2 SLPNO T03060233 10311 20222 \$

METAR KAIZ 131856Z AUTO 28006KT 10SM SCT034 32/24 RMK AO2 SLPNO T03170239 \$

METAR KAIZ 131956Z AUTO VRB05KT 10SM FEW038 33/23 RMK AO2 SLPNO T03280233 \$

Camdenton Memorial-Lake Airport (KOZS), Camdenton, MO, 8nm S, AWOS, elv. 1061 ft

METAR KOZS 131555Z AUTO 27009KT 10SM SCT016 SCT022 28/21 A2990 RMK AO2

METAR KOZS 131635Z AUTO 29011KT 10SM SCT027 30/21 A2990 RMK AO2

METAR KOZS 131655Z AUTO 30009G16KT 10SM SCT027 30/21 A2990 RMK AO2

METAR KOZS 131715Z AUTO 31009KT 10SM BKN027 30/21 A2990 RMK AO2

Accident 1715Z

METAR KOZS 131735Z AUTO 28007KT 250V320 10SM SCT027 30/21 A2989 RMK AO2

METAR KOZS 131755Z AUTO 31006KT 10SM SCT027 31/21 A2989 RMK AO2

METAR KOZS 131815Z AUTO 32003KT 10SM CLR 31/21 A2988 RMK AO2

METAR KOZS 131835Z AUTO 31008KT 10SM SCT034 31/21 A2989 RMK AO2

METAR KOZS 131855Z AUTO 29006KT 10SM SCT038 32/21 A2988 RMK AO2

Floyd W. Jones Lebanon (KLBO), LEBANON, MO, 27nm S, AWOS, elv. 1320 ft

METAR KLBO 131555Z AUTO 25011KT 10SM CLR 28/21 A2992 RMK AO2


SPECI KLBO 131635Z AUTO 27011G16KT 10SM SCT024 30/21 A2992 RMK AO2

METAR KLBO 131655Z AUTO 27011G15KT 10SM BKN026 30/20 A2992 RMK AO2

METAR KLBO 131715Z AUTO 27010KT 10SM SCT028 31/21 A2992 RMK AO2

METAR KLBO 131735Z AUTO 28010KT 10SM SCT030 31/20 A2990 RMK AO2

METAR KLBO 131755Z AUTO 31006KT 10SM SCT034 32/20 A2991 RMK AO2
 METAR KLBO 131815Z AUTO 31006KT 10SM SCT034 32/20 A2990 RMK AO2
 METAR KLBO 131835Z AUTO 32007KT 10SM SCT036 32/20 A2990 RMK AO2
 METAR KLBO 131855Z AUTO 32008G14KT 10SM SCT036 32/20 A2990 RMK AO2



No inflight weather advisories current for the area, i.e. no SIGMET, Convective SIGMET, Center Weather Advisories, of AIRMETs.

Don't see any major weather issues.

Donald Eick
 NTSB Senior Meteorologist
 Office of Aviation Safety
 Operational Factors Division (AS-30)
 490 L'Enfant Plaza East, SW
 Washington, DC 20594

