



Aircraft Discrepancy Record

C150K – N6059G

Date: 12/9	Discrepancy + Hobbs/Tach: 8024.9 L side fuel tank burns slower than R side	PIC Signature: 
MEL Item? Y/N N/A	Differed? yes - until next annual	Expected Repair Date: 1 mar 23
Repair Date: 15 Aug 23	Corrective Action: CND during annual	MX Signature: 

PIC Signature: