

CEN23FA410

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Airplane accident site (NTSB Photo)



Photograph 2 - Side view of airplane at accident site (NTSB Photo)



Photograph 3 - Ignition Distributor cap with scoring (NTSB Photo)



Photograph 4 - Ignition distributor rotor (NTSB Photo)