



Mitchell Gallo
Senior Aerospace Engineer
Aviation Safety, Central Region

Date: 10/27/2022

Subject: CEN23LA005

Contact: Frederick McMillan, Inspector, FAA

Frederick McMillan reported that the private rated student pilot was receiving flight instruction toward an airplane checkout in an L-16 at the time of the accident.

Frederick McMillan reported that the aircraft's last annual inspection was dated June 10, 2022, and the engine serial number was 3485-6-12.