

NATIONAL TRANSPORTATION SAFETY BOARD

ACCIDENT NUMBER:

RETENTION / RELEASE OF WRECKAGE RELATED TO ACCIDENT NUMBER ►

CEN23LA014

For Use in All Modal Investigations

REGISTERED OWNER (name and address) CCC Cornerstone Capital Consulting LLC [REDACTED]		IDENTIFICATION NUMBER N84LT	
		MAKE Diamond	
LOCATION Dallas, TX	DATE OF ACCIDENT 10/15/22	MODEL DA62	
RETAINED BY NTSB REPRESENTATIVE Michael J Folkerts		TITLE Aviation Safety Inspector	DATE 3/29/23
The National Transportation Safety Board has ☐ has not ☒ completed its investigation of the wreckage described above. All recovered wreckage except that listed in the evidence control form(s) is hereby released.			
☐ NO PARTS RETAINED			
RELEASED BY NTSB REPRESENTATIVE Michael J Folkerts		TITLE Aviation Safety Inspector	DATE 3/29/2023
(This section may be acknowledged by a person, not the owner or owner's representative, who has knowledge of the disposition of the recovered wreckage and its parts. Such acknowledgement does not place responsibility for disposition of the wreckage upon that person.)			
I HEREBY ACKNOWLEDGE:			
☒ Receipt of the above described wreckage.			
☒ Removal of the parts, if any, listed in the evidence control form(s).			
PERSON MAKING ACKNOWLEDGEMENT Gary Clay		TITLE President	DATE 4/25/23
ADDRESS [REDACTED]		PHONE NUMBER & EMAIL [REDACTED]	
REMARKS:			
The following items have been retained for the investigation:			
Alternator(Left) - Mahle, P/N: E4A-91-400-000, S/N: AB# 01217, P/N:AAL5106, S/N:11.204.500 17-192			
Alternator(Right)-Mahle, P/N: E4A-91-400-000, S/N:AB1# 01211, P/N:AAL5106, S/N:11.204.500,17-192			
Concorde Battery - Lead Acid - P/N RG24-15, S/N 40976083; Battery Cables			
Diamond Aircraft Hydraulic Power Pack, P/N D67-9029-13-00, S/N 0074			
Left and Right Alternator Regulators, Austro Engine E4, P/N - E4A-91-200-000-011, S/N - None, Date of Manufacture: 11/2017 Charge #: 1927667			
Electronic Control Units (EECUs) - Austro Engine, P/N E4PC-92-000-000, S/N 2024 (left), 2025 (right)			