



Jason Aguilera
Senior Air Safety Investigator
Aviation Safety - Central Region

Date: November 9, 2022

Subject: N1855K, Luscombe 8E

Contact: John Barr - Pilot

John Barr contacted me through the NTSB Communications Center to report an airplane accident that occurred about 1130 central standard time in Bridgeport, Texas. He reported that while landing runway 18, the airplane encountered winds that resulting in a loss of control and a ground loop.

When asked about any mechanical problems he responded that there were no problems with the airplane. The pilot described the airplane as "totaled." He said there was damage to the right main landing gear, right wing spar damage, and fuselage damage.