



Photo 1 – Right side of N282TX in a hangar (Source: FAA)



Photo 2 – Empennage of N282TX in a hangar (Source: FAA)



Photo 3 – Nose of N3333E (Source: FAA)



Photo 4 – N3333E propeller blade tip damage (Source: FAA)