



Timothy Sorensen
Sr. Aviation Accident Investigator
Aviation Safety - Central Region

Date: November 29, 2023
Subject: CEN23LA112 - Houston, Texas
Contact: Thomas Sully - Honda Aircraft Company

Mr. Sully provided the following information regarding the airplane:

- The airplane is equipped with a tail-mounted speed brake which is deployed manually by the pilot. The airplane is not equipped with wing-mount speed brakes or ground spoilers.
- The engines are not equipped with thrust reversers.
- The airplane has a crosswind limitation of 20 knots as noted in the flight manual. This is due, in part, to the low wing position (short landing gear) which limits the allowable bank angle during the landing flare.

----- end of summary -----