



Timothy Sorensen
Sr. Aviation Accident Investigator
Aviation Safety - Central Region

Date: March 9, 2023
Subject: CEN23LA123 - Erie, Colorado
Contact: Insp. Kurt Skultin, FAA Denver FSDO

Insp. Skultin reported that he and another inspector, Jay Dankoff, had examined the airplane after the accident. The inspectors observed a definite upward bend on the right wing from the root to the tip which was not noticeable in the damage photos. They were informed that the wing was going to be replaced rather than being repaired.

----- end of summary -----