



Timothy Sorensen  
Sr. Aviation Accident Investigator  
Aviation Safety - Central Region

**Date:** May 22, 2023  
**Subject:** CEN23LA130 - Dekalb, Texas  
**Contact:** Aaron Heath Lawrence - Pilot

Mr. Lawrence recalled hearing the main rotor speed decay and then looking at the instruments to confirm that the engine and rotor speeds were below the green arc. He stated that the low rotor speed warning system did not activate before the accident.

----- *end of summary* -----