

Rutt Brian

From: Kelly <[REDACTED]>
Sent: Tuesday, March 21, 2023 3:14 PM
To: Rutt Brian
Subject: Re: 6120.1
Attachments: 6120.1.pdf

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

N789TB, personal Part 91 flight.
New ELT was installed weeks prior, to match the new IFD 540, which was not complete in installation.
S/N 1919 for the airplane
year is 1999
Airworthiness: Normal
Tricycle retractable gear.
engine: TIO-540.
Rated power 250 BHP
Variable pitch prop. (Book lost in airplane).
Annual inspection from [REDACTED] from LNC airport.
Airplane was in good shape. I do not fault [REDACTED]

On Tue, Mar 21, 2023 at 3:54 PM Kelly <[REDACTED]> wrote:

On Tue, Mar 21, 2023 at 2:11 PM Rutt Brian <[REDACTED]> wrote:

Brian Rutt

Air Safety Investigator

National Transportation Safety Board

[REDACTED]

Aurora, Colorado 80011

Office: [REDACTED]

Fax: [REDACTED]

[REDACTED]