

Carburetor Icing Probability Graph – CEN23LA166

Airplane: Protech PT-2, N44048

Engine: Lycoming O-235-L2C

Fuel: Unknown

Accident Date: 04/24/2023

Accident Location: Columbia, MO

Accident Time: 1900 cdt

Weather: KBXA 242355Z AUTO 02004KT 10SM CLR
21/09 A3002 RMK AO2 T02100094 10246 20206

Celsius to Fahrenheit Conversion:

Temperature, 21° C = 69.8° F

Dew Point, 9° C = 48.2° F

Source: Federal Aviation Administration

Special Airworthiness Information Bulletin CE-09-35

Carburetor Icing Prevention

