

DATE 2021 19	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
5.13				ENGINE DISASSEMBLED FOR OVERHAUL, CASE
SMOH	⊕			CERTIFIED BY CSI, CRS HAHRO960, THE FOLLOWING
				CERTIFIED BY AEA, CRS LHA533K - CRANKSHAFT,
				RODS, GEARS, CARB OVERHAULED BY A/C CARB CRS
				10FR546Y, MAGNETO OH BY A/C IGN SERVICE, CRS
				5KHR557C, CYLINDERS OH AND BUILT TO STD
				BY SALS A/C CYLINDERS P3317502. ALL REQD PARTS
				REPLACED PER LYCOMING MSB 740 N. SEE IN-
				CLUDED 8130 FORMS & RECEIPTS. ENGINE ASSEMBLED
				AFTER OILWASH & PRIMING AS REQD, USING
				76 SERIES LYCOMING OVERHAUL MANUAL, AND
				LYCOMING TABLE OF LIMITS FOR TORQUE VALUES,

DATE 2021 19	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
5113				ENGINE TO BE PRE OILED PER LYCOMING SI 1241C
SMOH	⊖			ENGINE TO BE BROKEN IN PER LYCOMING SI 1421C
				AFTER WHICH CAN BE CONSIDERED OVERHAULED
				ENGINE MOUNT EARS THAT ATTACH TO THE CRASE
				STILL BE PERFORMED AFTER 100 OPERATING HRS
				PER ADT 9.18.03R2 - SI 1380.
				APPROVED BY [REDACTED] APP [REDACTED]