



Brian Rutt
Air Safety Investigator
Central Region

Date: 5/29/2023

Subject: CEN23LA212

Contact: Harvey Songer
Owner - Kin-Co Ag Services

During a phone conversation with Mr. Songer, he reported the pilot of N6678Q departed a private airstrip used for agricultural operations. Mr. Songer stated that the accident pilot turned "a little premature" after taking off with a load of fertilizer. Additionally, he stated there was a wind shift and the accident airplane happened to settle over a levy and the wheels caught terrain.