



Photo 1 – Bent engine mount (Photo from FAA)



Photo 2 – Broken engine mount (Photo from FAA)